Portland, Maine



Yes. Life's good here.

Danielle P. West-Chuhta Corporation Counsel

Michael I. Goldman Associate Counsel Anne M. Torregrossa Associate Counsel Victoria E. Morales Associate Counsel

December 1, 2016

NOTICE OF INTENT TO PROSECUTE

To Whom it May Concern,

Please see the attached Notice of Violation and Order to Correct from the City of Portland Fire Prevention Bureau. The Fire Prevention Bureau has referred this matter to me for prosecution in the event that you do not complete and return the required plan of action by the date contained in the Notice of Violation. Your failure to comply will result in the issuance of a summons for you to appear in court, and the imposition of civil penalties in the minimum amount of \$100 per violation per day.

Please contact the Fire Prevention Bureau at (207)874-8400 to resolve these outstanding violations. I look forward to your anticipated cooperation and appreciate your efforts to help keep the citizens of Portland safe.

Sincerely,

Anne M. Torregrossa

Associate Corporation Counsel

hme Tonequoso

City of Portland

CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

December 1, 2016

Responsible Party 1:				
ROUSE REGINALD				
15 HONEYSUCKLE LN				
SCARBOROUGH , ME 04074				
Location	CBL	Inspection Date		
Location 365 WOODFORD ST	CBL 122 F017001	Inspection Date 11/18/2016		
		_		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 12/30/2016. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED, OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.3.1, 4.3.2 BUILDING ADDRESS NOT MARKED ON BUILDING; 4.3.1 Signs shall be located in a position readily visible as approaching from the main access and approved by the Fire Department. Signs shall be illuminated or retro reflective on a contrasting background and the letter(s) size shall be approved by the Fire Department. 4.3.2 Street Address shall be clearly marked on the front of the building and building sign as approved by the Fire Department. Apartment 2 is incorrectly labeled as Apt 1 at the entrance off the driveway (Woodford St side).	
NFPA 101- 7.5.1.1 EXIT OBSTRUCTED ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. Egress from the second and third floor via the front stairwell (Stevens Ave side) requires the occupants to open an additional (non fire rated) door that divides the stairwell.	IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced.
NFPA 101- TABLE 8.3.4.2 UNRATED WINDOWS ARE NOT PERMITTED IN EXIT STAIRS; Fire window assemblies are not permitted in vertical shafts (including stairways, exits, and refuse chutes). Windows in apartment doors shall have the same fire rating as the door and assembly	//

Violation		Proposed Date of Completion
from an open floor area, continuous pass exit shall be maintained and shall be arra	QUIRED; Where exits are not immediately accessible ageways, aisles, or corridors leading directly to every nged to provide access for each occupant to no less, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4.	//
	e a small door at the back of a closet for a second bor, they are required to break a pain of glass and blt.	
conducted, records for manual inspection extinguisher, on an inspection checklist n	INSPECTION TAG; Where manual inspections are as shall be kept on a tag or label attached to the fire naintained on file, or by an electronic method. as and the basement require an inspection and tag	//
NFPA 720- 5.5.6.1 CO ALARMS REQUI	RED; The performance, location, and mounting of direct action, evacuation or relocation of the occupants or staff, shall comply with the	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
that states fire door assemblies for vertical chutes) are rated and required for 1 hour	OR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 al shafts (including stairways, exits, and refuse . s and any doors that open into the stairwell.	//
VIOLATOR CERTIFICATION		
· ·	within the timeframes provided. If I require addite Prevention Bureau prior to the deadline to requent to grant or deny.	1 0
	onsibility to schedule a reinspection of my proper ure to schedule a reinspection shall be deemed an	
	, I understand that I am liable for penalties pursua and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		

Fire Prevention Bureau

Date