
CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400



NOTICE OF VIOLATION AND ORDER TO CORRECT

September 20, 2017

Responsible Party 1:						
Howell Holland R						
747 E Main St						
Yarmouth, ME 04096						
Location	CBL	Inspection Date				
41 REVERE ST	124 J015001	9/5/2017				
Lnspector	Inspection Type	Status				
Daniel Dyer	FP Routine Inspection	Failed				

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 10/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion	
NFPA 101- 7.2.1.8.1 FIRE DOOR(S) MUST SELF-CLOSE; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3. Need self closer 2nd floor front	12-1-17	
NFPA 70- 590.6 EXTENSION CORDS; Ground-fault protection for personnel for all temporary wiring installations shall be provided to comply with 590.6(A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment, or similar activities. Red extension cord in basement to first floor used for permanent wiring	12/1/17	
NFPA 70 MISSING BOX COVERS; Refer to NFPA 70, National Electrical Code, on standards for missing box covers. basement	12/1/17	
NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour. From basement entrance to rear egress	12/1/17	
FINAL DATE OF COMPLETED VIOLATION(S)	//	
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)	//	

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

VIOLATOR CERTIFICATION


I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agreement, I understand that I am liable for penalties pursuant to the City of Portland Code of Ordinances $\S\S$ 1-15 and 10-25, and 30-A M.R.S. \S 4452 and may be subject to further legal action.

Date	53 7 6 °	Responsible Party
Date		Responsible Party
SEEN AND AGREED		
		Fire Prevention Bureau

City of Portland Fire Prevention Bureau



Re: 41 Revere St CBL 124 J015001

I am happy to correct the deficiencies noted in your Notice of Violation. Since I have very recently had major surgery, I need some time to recover before able to physically undertake the corrections. Therefore I propose to have remedies completed by 12-1-17.

Sincerely,

Holland R Howell

MA Harry