

Permitting and Inspections Department Michael A. Russell, MS, Director

November 15, 2017

MILLER MARKOS S 17 ATLANTIC ST PORTLAND, ME 04101

CBL: 125 D003001

Certified Mail 7014 1820 0001 4049 5280

Located at: 62 LINCOLN ST

Dear MILLER MARKOS S,

An evaluation of the above-referenced property on 11/15/2017 shows that the structure fails to comply with Chapter 10 of the Code of Ordinances of the City of Portland, Fire Prevention and Protection. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 90 days of the date of this notice. A re-inspection of the premises must occur on or before 02/22/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection. Sincerely,

Matthew Sarapas
Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager MILLER MARKOS S		Inspector Matthew Sarapas	Inspection Date 11/15/2017
Location	CBL	Status	Inspection Type
62 LINCOLN ST	125 D003001	Violations Exist	Housing Safety Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

1) 210

Violation:

ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes:

Third floor rear bedroom window not egress compliant

Comments: