



Install Date: 5/10/2017
Jewish Community Alliance
57 Ashmont Street
Portland, ME 04101
Cintas Fire Protection
603-717-7300

Cintas Fire Protection
3 Tallwood Drive
Bow , NH 03304
Cintas Fire Protection
603-717-7300
quinnj@cintas.com
JQ

Notes

Fusible Links:

=> To determine actual fusible link ratings, temperature readings must be taken during peak cooking time.

Jewish Community Alliance:

Note 1 => Nozzle: 1F x 4: (Range: 8 burners) nozzle position: 40-48 in., front edge of burner, nozzle flats parallel with burner front-to-rear centerline, aimed at center

System 2:

Note 2 => Nozzle: 1F x 4: (Range: 8 burners) nozzle position: 40-48 in., front edge of burner, nozzle flats parallel with burner front-to-rear centerline, aimed at center