CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

November 4, 2016

Responsible Party 1: Nguyen Guang 32 ARLINGTON ST #1	please fix to able to rece	Quany otherwis	I won 14
PORTLAND, ME 04101 Location 32 ARLINGTON ST	CBL 125 Q004001	Inspection Date	
Inspector David Petruccelli	Inspection Type FP Routine Inspection	Status Failed	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must complete the proposed date of completion column by proposing a reasonable timeframe to remedy each violation. This form must be received by the Fire Prevention Bureau no later than 1 1/30/2016. The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

YOUR FAILURE TO SUBMIT A PLAN OF ACTION BY THE DATE PROVIDED,
OR TO CORRECT ANY VIOLATION WITHIN THE APPLICABLE TIME FRAME, MAY RESULT IN
LEGAL ACTION AGAINST YOU, THE IMPOSITION OF CIVIL PENALTIES, AND THE PURSUIT OF
OTHER LEGAL REMEDIES.

Violation	Proposed Date of Completion	
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED, 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. Front and rear unit doors shall be labeled, office door marked	06/01/2017	
NFPA 101-7.2.4.3.1 FIRE BARRIER REQUIRES MAINTENANCE; Fire barriers separating buildings or areas between which there are horizontal exits shall have a minimum 2-hour fire resistance rating; unless otherwise provided in 7.2.4.4.1, and shall provide a separation that is continuous to the finished grounded level. Extra doorways from units to egress path	01 /01 /2018 not quiet sure fl request	e dease
notification appliances used to initiate or direct action, evacuation of relocation of the	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.	32-7 (-1
through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.	

	•	
Violation		Proposed Date of Completion
NFPA 101-31.3.2.1.1 BOILER PROTEC 31.3.2.1.1 shall be protected as indicated than a single dwelling unit (minimum sepa Sprinkler for gas water heaters in paseme		06/01/2017
NFPA 101-8.3.4.2 60 MINUTE FIRE DO	OR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 il shafts (including stairways, exits, and refuse	01/01/2018 as it does require more money than I could
understand that I must contact the Fire	within the timeframes provided. If I require add Prevention Bureau <u>prior to the deadline</u> to reque	afford to replace itional time to comply. I the door
have been remedied to do so. My failuviolations have not been remedied. If I fail to comply with this agreement,	onsibility to schedule a reinspection of my proper to schedule a reinspection shall be deemed at Lunderstand that I am liable for penaltics pursuand 10-25, and 30-A M.R.S. § 4452 and may be	and to the City of
Date 2/17	Responsible Party	
Date:	Responsible Party	1
SEEN AND AGREED U 27/17 Date	Fire Prevention Bureau	17
	•	
The second secon		•