


Affordable Fire Protection
 277 Spears Corner Road
 West Gardiner, Me. 04234
 207-512-4464



- *Portable Fire Extinguishers Service
- *Restaurant Suppression Systems
- *Fuel Island Suppression Systems
- *Emergency & Exit Lighting
- *24 Hour Emergency Service

Date: 12-18-15
 Tech: WL

Kitchen Range Hood Report

Customer Name: Woodford's F+B
 Site Address: 660 Forest Ave
Portland ME

System Installed in accordance w/mfg ul listing Yes No (if not UL 300, see Other)
 Manufacturer, quantity & size of each cylinder bottle? Protex 11 (2) 460h
 Manufacturer date / Hydrostatic test date 2013 2013 mfg/hydro
 Location of each cylinder bottle? Right of hood
 Any visible rust or physical damage on each bottle? Yes / No (If yes, see other)
 Cylinder & bracket securely mounted & cleaned? Yes / No
 Pressure gauge on cylinder bottle in proper operating range? Yes / No / N/A
 Ansul cartridge weight? Amerex cartridge in operating range? N/A
 If P/C, R/G A+, Kidde KRS or XV: date Co2 actuator cartridge replaced? 12-15 N/A
 Type of Auto Shut Downs Gas / Electric / Both
 If gas appliances, is there an automatic gas shut-off valve? Type? Yes / No / Manual / Electric
 If electric appliances, is there an automatic electrical shut off? Yes / No / N/A
 Is system hooked up to building fire alarm system? Yes / No
 Does system have a manual pull station? Yes / No (If No, See Other)
 Pull station tested, sealed, tagged Yes / No / N/A
 Total length of excess cable at manual pull release? 3" N/A
 EMT conduit and link line free of grease build up? Yes / No (If No, See Other)
 Are all corner pulley caps in place on all EMT (G/V, P/S & L/L)? Yes / No
 Piping and Nozzles free of grease build up +/- or removed & cleaned? Yes / No
 All nozzles checked, and cleaned and have proper caps / seals? Yes / No
 All piping, EMT & nozzles properly bracketed, secure & tight? Yes / No
 Does hood, duct & plenum have proper type & quantity of nozzles? Yes / No (If No, See Other)
 Total number of nozzles? Duct=2 Plenum=2 Appliance=2
 Total number of fusible links changed? 1 360 K / A / ML 5 450 K / A / ML 1 500 K / A / ML
 Fan Warning Sign on Hood? Yes / No
 System reset for proper operation & safety removed? Yes / No
 System bottle properly tagged & punched? Yes / No
 Does site have a Class K fire extinguisher for each hood? Yes / No (If No, See Other)
 Customer shown how to manually operate system? Yes / No
 Exhaust fan in working order Yes / No

Cooking appliance locations: Left to Right & Nozzle position

<u>Ovens</u>	<u>grill</u>	<u>char</u>	<u>sed char</u>	<u>000</u>
			<u>W/A Nozzle</u>	<u>000</u>

Comments / Recommendations:

- Has system been Red Tagged / out of Compliance/Why _____
- AFP recommends upgrading non compliant system to UL 300 Standards
- Appliances shown above need additional nozzles to be properly protected & up to Code
- Other did full function test all working properly (WL) 12-18-15

[Signature]
 Reviewed & Received By