

21. Geotechnical Report

The existing foundation is at a similar depth to that of the new building. The soils in the area are sandy soils; suitable for development.