

Permitting and Inspections Department Michael A. Russell, MS, Director

October 31, 2017

WILLIAMSON WILLIAM T & 69 HOPKINS RD HAMPDEN, ME 04444

CBL: 132 E010001

Located at: 36 LAWN AVE

Certified Mail 70141820000140495082

Dear WILLIAMSON WILLIAM T &,

An evaluation of the above-referenced property on 10/28/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 12/05/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Kevin Hanscombe

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager WILLIAMSON WILLIAM T &		Inspector Kevin Hanscombe	Inspection Date 10/28/2017
Location	CBL	Status	Inspection Type
36 LAWN AVE	132 E010001	Violations Exist	Housing Safety Inspection

Unit No.

1) 210

Violation:

Code

ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

Area

Compliance Date

NFPA 101 (2009) 24.2.2.3.3

Int/Ext

Floor

Notes:

3rd floor bedrooms missing egress window (note* windows lower than 18" from floor will also need to

be tempered glass)

2) 211

Violation:

OTHER

Notes:

loose wireing on 3rd floor needs to be fixed by licensed electrician.

Comments: