

7/19/02 checked deck in rear - after the fact
permit - setbacks appear OK - need handrails on steps
⊗ no guard system on RT side of steps, Trex/decks etc.
JMM

116104 complete. Above issues have been corrected JN