

Permitting and Inspections Department Michael A. Russell, MS, Director

August 2, 2017

CLARIOT RAFAEL W & 11 PARK RD WINDHAM, ME 04062

CBL: 137 B004001

Located at: 66 IRVING ST

Certified Mail 70153010000002010839

Dear CLARIOT RAFAEL W &,

An evaluation of the above-referenced property on 06/19/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 09/08/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Kevin Hanscombe

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager CLARIOT RAFAEL W &			Inspector Kevin Hanscombe	Inspection Date 6/19/2017
Location 66 IRVING ST		CBL 137 B004001	Status Violations Exist	Inspection Type Housing Safety Inspection
Code	Int	t/Ext Floor	Unit No. Area	Compliance Date
1) 205 Violation:	station (interco	nnected) photoel	ectric smoke alarms must be	amily Dwellings: Single-station or multiple powered by the building electrical system e positioned correctly on walls or ceilings:

NFPA 101 (2009) 24.3.4.1(2)(3), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

Basement, 1st floor, 3rd floor (missing) 2nd floor needs to be moved ADDRESSED IMMEDIATELY

(1) within 21 feet of any door to a sleeping room and (2) in living areas separated by doors on each

2) 207

Violation:

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

Basement, 1st floor, 2nd floor, 3rd floor, ADDRESS IMMEDIATELY

level of the dwelling unit and (3) including the basement.

3) 205

Violation:

SMOKE ALARMS / LEVEL; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiplestation (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) within 21 feet of any door to a sleeping room and (2) in living areas separated by doors on each level of the dwelling unit and (3) including the basement.

NFPA 101 (2009) 24.3.4.1(2)(3), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

Additional smoke alarm for 1st floor front living room due to door being there (30 DAYS)

4) 206

Violation:

SMOKE ALARMS / BEDROOMS; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: in all sleeping rooms.

NFPA 101 (2009) 24.3.4.1(1), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

Missing 3 bedrooms (30 DAYS)

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date 6/19/2017
CLARIOT RAFAEL W	&	Kevin Hanscombe	
Location	CBL	Status	Inspection Type
66 IRVING ST	137 B004001	Violations Exist	Housing Safety Inspection

5) 210

Violation: ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a

free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with

an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes: 3rd floor has 2 bedrooms front and back with no viable escape window. Current windows are too small.

Will have contractor lined up and proper permits if necessary applied for with in 30 days

6) 211

Violation: OTHER

Notes: Storage/workshop barn attached to rear of property has primary 2nd egress through it from 2nd floor

unit. Too much storage (fire load) and no smoke alarm. LL will add aditional photo electric smoke alarm (hardwired) outside of 2nd floor unit kitchen area in the barn near the door. Licensed electrician

lined up and any permits necessary applied for by 30 days

7) 211

Violation: OTHER

Notes: Numerous missing switch and plug wall plates, loose wiring in basement and missing junction boxes

along with missing junction box covers. Licensed electrician lined up and any permits necessary

applied for by 30 days

8) 211 Exterior

Violation: OTHER

Notes: Rotten railings and steps outside. Have a plan of action to address these with in 30 days.

Comments: