## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

December 7, 2017

Responsible Party 1:				
ROULEAU ERNEST				
132 OCEAN AVE				
PORTLAND, ME 04103				
Location	CBL	Inspection Date		
<b>Location</b> 132 OCEAN AVE	CBL 138 D014001	Inspection Date 11/13/2017		
		*		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 12/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. Label all apartment doors, front and rear entryways.	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.  A hardwired carbon monoxide alarm is required in the basement with battery backup. A combination photoelectric hardwired smoke/Carbon monoxide is also acceptable.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  In apartment 2, an hardwired photoelectric smoke alarm with battery back-up is required outside the front bedroom and inside the rear bedroom.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.  Remove all storage in the front stairwell outside apartment 2.	//
NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; The areas described in Table 31.3.2.1.1 shall be protected as indicated: Boiler and fuel-fired heater rooms serving more than a single dwelling unit (minimum separation/protection is 1 hour or sprinklers) Install a domestic sprinkler head over each of the furnaces (2 total).	//

Violation		Proposed Date of Completion
that states fire door assemblies chutes) are rated and required	artments 1 and 2 must be 60 minute rated fire doors with self-	//
FINAL DATE OF COMPLETE	D VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
sufficient financial and techniquestions.  VIOLATOR CERTIFICA		t the Bureau with any
understand that I must contain is entirely within the Bureau  I further understand that it is	ons listed within the timeframes provided. If I require add act the Fire Prevention Bureau <u>prior to the deadline</u> to requests discretion to grant or deny.  It is my responsibility to schedule a reinspection of my prope to the deemed are actived.	uest an extension, which erty once the violations
If I fail to comply with this a	greement, I understand that I am liable for penalties pursues §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	