CITY OF PORTLAND

FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

June 28, 2017

SEAN AND NOLA FENNESSY 32 TREMAINE ST PORTLAND ME 04103

Location	CBL	Inspection Date
13 DINGLEY CT	143 A058001	2/3/2017
Inspector	Inspection Type	Status
David Petruccelli	FP Plan of Action	Violations Exist

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 7/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 31.3.3.2 INTERIOR FINISH ; Interior wall and ceiling finish materials complying with 10.2 shall be permitted as follows: (1) Exit enclosures- Class A or B (2) Lobbies and corridors- Class A or B (3) Other Spaces- Class A, B, or C. Panelling in stairwell, owner shall provide documentation of flame spread class or remedy the situation.	
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED ; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. All apartment doors must be labeled with their appropriate apartment number.	/
NFPA 101- 7.2.1.15.8 FIRE DOOR ASSEMBLY REQ REPAIR ; Door openings not in proper operating condition shall be repaired or replaced without delay. The basement door is required to be self closing.	/ /
NFPA 101- 7.5.1.1 EXIT OBSTRUCTED ; Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. There is storage in both the front and rear stairwells. There Is a dormer blocking egress from the third floor on the top of the stairs. Occupant need to duck around the obstruction.	//
NFPA 101- 7.2.8.5.1 HANDRAILS REQUIRED ON STAIRS ; All fire escape stairs shall have walls or guards and handrails on both sides in accordance with 7.2.8.4.1 (b). A continuous handrail is required in the rear stairwell from the top floor to the bottom.	/ /

Violation	Proposed Date of Completion
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED ; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.	//
There are no CO detectors in the basement or in the apartments.	
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.	//
Tires are being stored in the basement.	
NFPA 70- 4.10.8 DEFECTIVE LIGHT FIXTURE ; Luminaries shall be installed such that the connections between the luminaire conductors and the circuit conductors can be inspected without requiring the disconnection of any part of the wiring unless the luminaries are connected by attachment plugs and receptacles.	//
All light fixtures must have a light bulb to prevent a shock injury from the exposed wires.	
FINAL DATE OF COMPLETED VIOLATION(S)	//
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)	/

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau <u>prior to the deadline</u> to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agreement, I understand that I am liable for penalties pursuant to the City of Portland Code of Ordinances §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal action.

Date

Responsible Party

Date

Responsible Party

Date

Fire Prevention Bureau