## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

March 15, 2018

EWT 17 LLC 99 FISHERVILLE RD CONCORD NH 03301

Location	CBL	Inspection Date
1011 FOREST AVE	147 A024001	2/13/2018
Inspector	Inspection Type	Status
Aaron Bridges	FP Routine Inspection Commerci	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 3/30/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101-7.9.3 EMERGENCY LIGHTS REQUIRE MAINTENANCE; 7.9.3 Periodic Testing of Emergency Equipment 7.9.3.1 Required emergency lighting systems shall be tested in accordance with one of the three options offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3. 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for not less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2). (2) The test interval shall be permitted to be extended beyond 30 days with the approval of the authority having jurisdiction. (3) Functional testing shall be conducted annually for a minimum 1-1/2 hours if the emergency lighting system is battery powered. (4) The emergency lighting equipment shall be fully operational for the duration of the test required by 7.9.3.1.1(1) and (3). (5) Written records of visual inspections and tests shall be kept by the owner for inspection by the authority having jurisdiction.  Emergency light downstairs isn't working.	
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.	//
There are items blocking the access to the the electrical panels in the basement.	, , ,
NFPA 70- 590.6 EXTENSION CORDS; Ground-fault protection for personnel for all temporary wiring installations shall be provided to comply with 590.6(A) and (B). This section shall apply only to temporary wiring installations used to supply temporary power to equipment used by personnel during construction, remodeling, maintenance, repair, or demolition of buildings, structures, equipment, or similar activities.  Down in the basement in an office there is a cage for a gecko that has two work lights hanging above the cage for warmth. They are left on all night long and are powered by and extension cord plugged into a powerstrip.	//

Violation		Proposed Date of Completion
for missing box covers.	Refer to NFPA 70, National Electrical Code, on standards	//
· · ·	the first floor hallway, over the electrical panel.	
NFPA 70 MISSING COVER ON PANEL; Refer to NFPA 70, National Electrical Code, on requirements of missing cover on electrical panel.  A ceiling outlet box is missing the cover in the electrical utility room in the basement. The main electrical room has a panel missing a cover.		//
FINAL DATE OF COMPLETED VI		//
FIRE PREVENTION BUREAU RE-	INSPECTION OF COMPLETED VIOLATION(S)	//
	reject or modify any proposed plan of action, and may a capacity to complete the proposed plan. Please contact  N	=
•	listed within the timeframes provided. If I require addine Fire Prevention Bureau <u>prior to the deadline</u> to requ Escretion to grant or deny.	
•	v responsibility to schedule a reinspection of my proper y failure to schedule a reinspection shall be deemed an rd.	•
	ment, I understand that I am liable for penalties pursual 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be s	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	