


CITY OF PORTLAND
 FIRE PREVENTION BUREAU
 380 Congress Street, Portland, Maine 04101
 fireprevention@portlandmaine.gov
 (207) 874-8400



NOTICE OF VIOLATION AND ORDER TO CORRECT

May 17, 2017

Location 52 CANCO RD(On Target Off	CBL 147 C001001	Inspection Date 5/4/2017
Inspector Brad James	Inspection Type FP Routine Inspection Commerci	Status Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 6/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 7.10.1.1 EXITS CLEARLY VISIBLE OR CONSPICUOUSLY INDICATED; Where Required: Means of egress shall be marked in accordance with section 7.10 where required in Chapters 11 through 43. Install signs per code.	6/5/17
NFPA 101-7.9 EMERGENCY LIGHTING In office area there is a light not working.	6/5/17
NFPA 101- 7.9.1.1 EMERGENCY LIGHTING REQUIRED; Emergency lighting facilities for means of egress shall be provided in accordance with Section 7.9 for the following: (1) Buildings or structures where required in Chapters 11 through 43 (2) Underground and limited access structures as addressed in Section 11.7 (3) High-rise buildings as required by other sections of this code (4) Doors equipped with delayed-egress locks (5) Stair shaft and vestibule of smokeproof enclosures, for which of the following also apply: (a) The stair shaft and vestibule shall be permitted to include a standby generator that is installed for the smokeproof enclosure mechanical ventilation equipment (b) The standby generator shall be permitted to be used for the stair shaft and vestibule emergency lighting power supply (6) New access-controlled egress doors in accordance with 7.2.1.6.2 Install lighting to meet current code.	6/15/17
NFPA 101- 7.2.1.1.1 FIRE DOOR(S) REQUIRE REPAIR; A door assembly in a means of egress shall conform to the general requirements of Section 7.1 and to the special requirements of 7.2.1. The horizontal sliding fire door between the offices and the warehouse needs to be repaired or replaced.	6/15/17

Violation	Proposed Date of Completion
FINAL DATE OF COMPLETED VIOLATION(S)	6 / 15 / 2017
FIRE PREVENTION BUREAU RE-INSPECTION OF COMPLETED VIOLATION(S)	_ / _ / _

The Bureau reserves the right to reject or modify any proposed plan of action, and may require evidence of sufficient financial and technical capacity to complete the proposed plan. Please contact the Bureau with any questions.

VIOLATOR CERTIFICATION

I agree to remedy the violations listed within the timeframes provided. If I require additional time to comply, I understand that I must contact the Fire Prevention Bureau prior to the deadline to request an extension, which is entirely within the Bureau's discretion to grant or deny.

I further understand that it is my responsibility to schedule a reinspection of my property once the violations have been remedied to do so. My failure to schedule a reinspection shall be deemed an admission that the violations have not been remedied.

If I fail to comply with this agreement, I understand that I am liable for penalties pursuant to the City of Portland Code of Ordinances §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be subject to further legal action.

6/13/2017

 Date

[Signature] Pres. Ltd

 Responsible Party

 Date

 Responsible Party

SEEN AND AGREED

6/15/17

 Date

[Signature] #17

 Fire Prevention Bureau