

•
•
•
•
•
•
•

389 Congress St.Rm 315
Portland, ME 04101
Phone: (207)874-8700
Fax: (207)874-8716

facsimile transmittal

To: Dennis Paul Watson **From:** Mike Nugent

Fax: 303-904-4866 **Date:** May 19, 2003

Phone: 303-904-4837 **Pages:** 1

Re: Morrill St. Associates 57 Bell St.150b001

Urgent For Review Please Comment Please Reply Please Recycle



I have started the review of the above project and have questions:

- 1) Attached are required certifications and Section 1705. of the 1999 BOCA Code which deals with Special Inspections, Please complete the forms and return them with a Statement of Special Inspection. This note applies to both the building and foundation plans.
- 2) There are hand written notes on the foundation plan, where these done by the engineer?
- 3) Your notes the "1996 BOCA Code" the City is under the 1999 BOCA Code.
- 4) Because the roof is 1:12, the roof design must be done in accordance with Section 7.3 of ASCE 7.
- 5) There is no Soils report as required by Section 1804.1 of the BOCA code.

• • • • •