CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

March 15, 2018

JONATHAN & LINDA SHUTE 685 SLIGO RD NO YARMOUTH ME 04097

| Location | CBL | Inspection Date |
|-----------------|-----------------------|------------------------|
| 827 STEVENS AVE | 152 A002001 | 2/8/2018 |
| Inspector | Inspection Type | Status |
| Chris Pirone | FP Routine Inspection | Failed |

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 3/30/2018.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

| Violation | Proposed Date of Completion |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|
| PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. Rear hallways only | // |
| NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3. rear door apt. #1 | // |
| NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour. Rear hallway at cellar entrances (2 doors) | // |
| NFPA 101- 4.5.3.4 MEANS OF EGRESS SHALL BE ILLUMINATED ; Lighting: Where artifical illumination is needed in a building or structure, egress facilities shall be included in the lighting design. | |
| NFPA 101- 7.1.10.2.1 DEBRIS INSIDE BUILDING; No furnishings, decorations, or other objects shall obstruct exits or their access there to, egress therefrom, or visibility thereof. Front hallway leading to attic space-debris needs to be removed | |
| NFPA 101- 7.2.2.4.2 HANDRAILS ARE NOT CONTINOUS; Required guards and hardrails shall continue for the full length of each flight of stairs. At turns of new stairs, inside handrails shall be continuous between flights at landings. Front and rear hallway | |

| Violation | | Proposed Date of Completion |
|----------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|
| those equipped through out with an exist | TOR EACH SLEEPING ROOM; In buildings other than sting, complete automatic smoke detection system, mmediate vicinity of the bedrooms and on all levels of | |
| door operable from the inside without the a clear opening of not less than 5.7 squand the height shall be not less than 24 | WS - INSUFF. SIZE; It shall be an outside window or ne use of tools, keys, or special effort and shall provide pare feet. The width shall be not less than 20 inches, inches. The bottom of the opening shall not be more PA 101 24.2.2.3.3 for a continuation of this code. | |
| NFPA 101- 31.2.2.5 ESCAPE WINDOW 7.2.4 shall be permitted. In all BR's | VS - SILL TOO HIGH; Horizontal exits complying with | |
| FINAL DATE OF COMPLETED VIOLA | ATION(S) | // |
| FIRE PREVENTION BUREAU RE-INS | PECTION OF COMPLETED VIOLATION(S) | // |
| | ct or modify any proposed plan of action, and may pacity to complete the proposed plan. Please contact | - |
| | ed within the timeframes provided. If I require add Tire Prevention Bureau <u>prior to the deadline</u> to requetion to grant or deny. | |
| · · | sponsibility to schedule a reinspection of my prope ilure to schedule a reinspection shall be deemed an | - |
| | nt, I understand that I am liable for penalties pursu 5 and 10-25, and 30-A M.R.S. § 4452 and may be s | • • |
| Date | Responsible Party | |
| Date | Responsible Party | |
| SEEN AND AGREED | | |
| Date | Fire Prevention Bureau | |