

## Permitting and Inspections Department Michael A. Russell, MS, Director

December 6, 2017

WHITE THERESE K & 54 FIELDSTONE LN FALMOUTH, ME 04105

CBL: 163 P006001

Located at: 3 FERNALD TER

Certified Mail 7013225069951601

Dear WHITE THERESE K &,

An evaluation of the above-referenced property on 12/06/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 01/10/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely

Kevin Hanscombe

Code Enforcement Officer

## CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager WHITE THERESE K &		Inspector Kevin Hanscombe	Inspection Date 12/6/2017
Location	CBL	Status	Inspection Type
3 FERNALD TER	163 P006001	Violations Exist	Housing Safety Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

1) 207

Violation:

Code

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

Area

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

Missing basement and 1st floor (combination units can be used where applicable)

Unit No.

2) 210

Violation:

ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Int/Ext

Floor

Notes:

2nd floor bedroom

Comments:

Re-inspection for detection must be must take place on or before 01/10/2018. A plan of action to address egress window can be submitted at that time.