

Permitting and Inspections Department Michael A. Russell, MS, Director

December 15, 2017

NORTON PROPERTIES LLC PO BOX 16 SCARBOROUGH, ME 04070

CBL: 168 F009001

Located at: 37 INVERNESS ST

Certified Mail 70132250000169951663

Dear NORTON PROPERTIES LLC,

An evaluation of the above-referenced property on 12/14/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 01/17/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Kevin Hanscombe

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager NORTON PROPERTIES LLC		Inspector Kevin Hanscombe	Inspection Date 12/14/2017
Location	CBL	Status	Inspection Type
37 INVERNESS ST	168 F009001	Violations Exist	Housing Safety Inspection

1) 207

Code

Violation:

CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

Area

Compliance Date

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Unit No.

Notes:

Missing basement

Int/Ext

Floor

2) 211

Violation:

OTHER

Notes:

missing junction box cover(s) and paper faced insulation needs to be covered or removed from

basement

3) 210

Violation:

ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes:

Escape windows all bedrooms.

Comments:

Re inspection for detection and other violations along with plan of action to address egress windows due on or before 01/17/2018. Please call 874-8557 to schedule your follow up.