

Permitting and Inspections Department Michael A. Russell, MS, Director

January 13, 2018

JONAITIS THOMAS A 133 SANDY HILL RD SOUTH PORTLAND, ME 04106

CBL: 168 M018001

Located at: 41 ALTON ST

Certified Mail 70172680000054981228

Dear JONAITIS THOMAS A,

An evaluation of the above-referenced property on 10/19/2017 shows that the structure fails to comply with Chapter 10. Article I. of the Code of Ordinances of the City of Portland, Fire Prevention and Protection. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises Shall occur within 30 days at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 10-25 of the Code.

This constitutes an appealable decision pursuant to Section III of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Kevin Hanscombe

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager JONAITIS THOMAS A		Inspector Kevin Hanscombe	Inspection Date 10/19/2017
Location	CBL	Status	Inspection Type
41 ALTON ST	168 M018001	Violations Exist	Housing Safety Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

1) 207

Violation:

CARBON MONOXIDE ALARMS / LEVEL: Carbon Monoxide Alarms - One and Two-Family Dwellings: Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes:

basement and 1st floor living area

2) 205

Violation:

SMOKE ALARMS / LEVEL; Smoke Alarms - One and Two-Family Dwellings: Single-station or multiplestation (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or ceilings: (1) within 21 feet of any door to a sleeping room and (2) in living areas separated by doors on each level of the dwelling unit and (3) including the basement.

NFPA 101 (2009) 24.3.4.1(2)(3), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes:

basement

3) 210

Violation:

ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes:

All bedroom

Comments:

Must schedule a re inspection for all NON escape window violations within 30 days of notice. Please call 874-8557 to schedule that appointment. During re inspection a plan of action to address escape window(s) violations will be submitted.