



DAILY CONSTRUCTION REPORT

Project: Osher Inn at Cedars

SWCE Project No.: 07-0503

Client: JHA Assisted Living Facility

Client's Rep.: John Watson

Date: 4-2-08

Weather: Sunny and windy, 30 - 40

Work in Progress: Interior and exterior fit-out, all trades.

General Observations, Discussions, Etc: As requested by C.M. Cimino we performed a site visit for the purpose of re-inspecting the anchors that were noted in our previous report (dated 3-24-08) as being incomplete. Based on our discussions with C.M. Cimino (Anthony), we understand that the few anchors not visible protruding through the double plate on the exterior walls were of insufficient length to penetrate the 3-inches of framing and were secured over the bottom plate during construction. At the time of our visit, the framing subcontractor was on site and in the process of installing epoxy anchors in through the plates in the shear and corridor walls as required. The practices we observed appeared to be consistent with the structural drawings and general industry procedures. We are not aware of any further deficiencies.

On Site: 10:00 – 10:30

Attachments: Photos

Sheet: 1 of 1

SWC Rep.: K. Gimpel

Rev. by: RED

P:\2007\07-0503 M - JHA Assisted Living, Inc. - Portland, ME - The Inn at Cedar - RED\DFR's\DFR 4-2-08 wood frame inspection.doc

GRAY, ME OFFICE

286 Portland Road, Gray, ME 04039, Tel (207) 657-2866, Fax (207) 657-2840, (E) infogray@swcole.com, (I) www.swcole.com

The SWCE field representative is on-site at the request of our client to provide construction materials testing and to observe and document construction activities. The contractor has sole responsibility for schedule, site safety, methods, completeness and quality of the work.

