CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

NOTICE OF VIOLATION AND ORDER TO CORRECT

April 13, 2017

Responsible Party 1:				
Larsson Eric				
65 Berkeley Street				
Portland, ME 04103				
Location	CBL	Inspection Date		
Location 572 BRIGHTON AVE	CBL 185 C013001	Inspection Date 3/29/2017		
		•		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

You must send this form to the Fire Prevention Bureau no later than 4/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 4.6.1, 4.6.2 UNIT/SUITE NUMBERS NOT MARKED; 4.6.1 Residential units shall be designated using numerals. 4.6.2 The first numeral of each residential unit shall be the floor designation. All apartment doors should be labeled for easy recognition from the street and from inside the stairwells as well.	//
NFPA 101- 7.2.1.15.8 FIRE DOOR ASSEMBLY REQ REPAIR; Door openings not in proper operating condition shall be repaired or replaced without delay. Add self-closing hinges to the fire doors for Apartments 3E and 2W in the front stairwell.	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6. Add hardwired CO detector in Apartment 3.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements. Replace the non-working smoke detectors in the baby room of Apartment 3 and outside the kitchen (dining room) of Apartment 2E.	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.

Violation		Proposed Date of Completion
equipment, including busbars, wiring te damaged or contaminated by foreign m corrosive residues. There shall be no di	-	//
that states fire door assemblies for vert chutes) are rated and required for 1 hou	OOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 cal shafts (including stairways, exits, and refuse ur. hinges for the extra stairwell door for apartment 2W.	//
FINAL DATE OF COMPLETED VIOLA	ATION(S)	//
FIRE PREVENTION BUREAU RE-INS	PECTION OF COMPLETED VIOLATION(S)	//
understand that I must contact the F is entirely within the Bureau's discrete I further understand that it is my rehave been remedied to do so. My faviolations have not been remedied. If I fail to comply with this agreement	If I require additive Prevention Bureau prior to the deadline to require to the deadline to require to the grant or deny. Sponsibility to schedule a reinspection of my proper illure to schedule a reinspection shall be deemed an anti-fit in I understand that I am liable for penalties pursuants I and 10-25, and 30-A M.R.S. § 4452 and may be seen and 10-25, and 30-A M.R.S.	test an extension, which ty once the violations admission that the ant to the City of
Date	Responsible Party	
Date SEEN AND AGREED	Responsible Party	
Date	Fire Prevention Bureau	