



Permitting and Inspections Department

Michael A. Russell, MS, Director

March 3, 2018

3A PROPERTIES
1227 CONGRESS ST
PORTLAND, ME 04102

CBL: 186 C027001**Mail****Located at: 18 BOLTON ST**

Dear 3A PROPERTIES,

An evaluation of the above-referenced property on 03/02/2018 shows that the structure fails to comply with Chapter 6, Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 60 days of the date of this notice. A re-inspection of the premises must occur on or before 05/04/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

A handwritten signature in black ink, appearing to read "KH", followed by a long horizontal line.

Kevin Hanscombe
Code Enforcement Officer

**CITY OF PORTLAND
HOUSING SAFETY OFFICE**

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager 3A PROPERTIES		Inspector Kevin Hanscombe	Inspection Date 3/2/2018
Location 18 BOLTON ST	CBL 186 C027001	Status Violations Exist	Inspection Type Housing Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 55.161					
Violation:	NFPA 101- 31.3.4.5.1 SMOKE DETECTOR EACH SLEEPING ROOM; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.				
Notes:	NFPA and Per Chapter 10 All smoke alarms must be located INSIDE the bedrooms and must be hard wired with battery back up and photoelectric. Licensed electrician to install (Permit Required). Also missing basement level smoke alarm				
2) 55.05					
Violation:	NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.				
Notes:	Missing basement, combination smoke and co alarms are allowed where possible.				
3) 55.051					
Violation:	NFPA 101- 7.2.1.8.1 DOORS SHALL BE SELF-CLOSING & SELF-LATCHING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise specified by 7.2.1.8.3.				
Notes:	All fire doors must also be self closing and self latching				
4) 55.395					
Violation:	NFPA 101- 31.3.1.1.1 VERTICLE OPENINGS SHALL BE PROTECTED; VERTICAL OPENINGS SHALL BE ENCLOSED OR PROTECTED IN ACCORDANCE WITH SECTION 8.6.				
Notes:	Damaged plaster in hallways				
5) 6-108.(b)					
Violation:	INTERIOR FLOORS, WALLS, CEILINGS AND DOORS; EVERY FLOOR, WALL, CEILING, AND DOOR SHALL BE IN A STRUCTURALLY SOUND CONDITION AND IN GOOD REPAIR AND SHALL BE SUBSTANTIALLY VERMIN PROOF.				
Notes:	Bathroom ceiling missing tiles and stained and cracked.				
6) 55.005					
Violation:	NFPA 101- 31.2.1.1 ESCAPE WINDOWS - INSUFF. SIZE; It shall be an outside window or door operable from the inside without the use of tools, keys, or special effort and shall provide a clear opening of not less than 5.7 square feet. The width shall be not less than 20 inches, and the height shall be not less than 24 inches. The bottom of the opening shall not be more than 44 inches above the floor. See NFPA 101 24.2.2.3.3 for a continuation of this code.				
Notes:	3rd floor missing escape window. Please see attached egress policy to correct				

**CITY OF PORTLAND
HOUSING SAFETY OFFICE**

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager 3A PROPERTIES		Inspector Kevin Hanscombe	Inspection Date 3/2/2018
Location 18 BOLTON ST	CBL 186 C027001	Status Violations Exist	Inspection Type Housing Inspection

7) 3.011

Violation: NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; THE AREAS DESCRIBED IN TABLE 31.3.2.1.1 SHALL BE PROTECTED AS INDICATED:
BOILER AND FUEL-FIRED HEATER ROOMS SERVING MORE THAN A SINGLE DWELLING UNIT
(MINIMUM SEPARATION/PROTECTION IS 1 HOUR OR SPRINKLERS)

Notes:

Comments: plan of action for egress window due in 30 days. Call 207-756-8169 to discuss. A re inspection must take place on or before 05/04/2018. Call 207-874-8557 to schedule re inspection



Permitting and Inspections Department
Michael A. Russell, MS, Director

Jonathan Rioux, Inspections Director

Information Bulletin: 2018-01

Secondary Means of Escape and Rescue Openings

Adopted: 02/02/2018 *MRR*

Background

The City of Portland has adopted the NFPA Life Safety Code (NFPA 101) and the NFPA Fire Code (NFPA 1), along with other building codes (MUBEC), which have minimum requirements for means of escape from residential dwellings, up to four stories in height.

NFPA 101 requires that new and existing dwellings provide for both a primary and a secondary means of escape from each sleeping room and living area.[1] NFPA 101 (2009) §§ 24.2.2.1.1, 31.2.1.2. A window may be used as the secondary means of egress or escape where the window is:

1. operable from the inside without the use of tools, keys, or special effort;
2. provides a net clear opening of not less than 5.7 sq. ft.;
3. not less than 20" wide;
4. not less than 24" high;
5. not more than 44" above the floor; and
6. meets one or more conditions for accessibility of fire department rescue apparatus.

Id. §§ 24.2.2.2.3.3, 31.2.1.2.

Windows in new construction have to meet the requirements of NFPA 101, as well as MUBEC, including the 5.7 sq. ft. net clear opening requirement. Note: The new construction provisions will also apply to replacement windows as part of the approval requirements for a change of use or occupancy.

Enforcement of Minimum Window Size

The City will generally not require existing windows to be replaced, even where they do not meet all of the above criteria numbered 1-6, as long as the existing windows meet certain minimum standards for safety.[2] The circumstances under which undersized, existing windows will be allowed to remain depends on:

1. When the existing window was installed,
2. The size of the window, and if
3. Changes are being proposed to the building.

Windows installed before 1976 will be considered acceptable to the City and do not need to be replaced, if the windows meet the minimum requirements outlined in the State Fire Marshal's "Policy for clarification



Permitting and Inspections Department
Michael A. Russell, MS, Director

Jonathan Rioux, Inspections Director

of existing egress windows” memo dated October, 17, 2013. These windows meet all of the requirements numbered 1-6 on Page 1 of this informational bulletin with the exception of number 2. Number 2 shall be replaced with, “2. provides a net clear opening of at least **3.3 sq. ft.** and an overall opening size of **5.0 sq. ft.** if all window parts are removed”.

Windows installed after 1976 must be replaced by windows meeting all of the requirements numbered 1-6 on Page 1 of this informational bulletin. This includes a net clear opening of not less than **5.7 sq. ft.**

Renovations or projects involving a change of use or occupancy, legalization of nonconforming units, or renovations to exterior walls. Where a renovation or project involves a change of use, the legalization of nonconforming units, or renovations to exterior walls, windows must be installed that meet all of the requirements numbered 1-6 on Page 1 of this informational bulletin.

Other renovations. The replacement window may be the same size as the existing window if:

1. No other renovations to the exterior wall are proposed,
2. No change of use or legalization of a nonconforming unit is proposed,
3. The window has a minimum net clear opening of at least **3.3 sq. ft.** for a double hung or,
4. **5.0 sq. ft.** for a casement-style, and,
5. Meets all of the other requirements numbered 1-6 on Page 1 of this informational bulletin.

However, when the rough opening for the replacement window is large enough to allow installation of a window with a minimum of **5.7 sq. ft.** net clear opening, that requirement must be met, even if the window operation is different than the original window. If it is not possible to meet the **5.7 sq. ft.** net clear opening, the replacement window must be the manufacturer's largest standard size window that will fit within the existing window frame or existing rough opening. The replacement window shall either be of the same operating style as the existing window or a style that provides for a greater window opening area than the existing window.

The City reserves the right to require installation or replacement of any window to meet the safety requirements of NFPA 1 and 101, MUBEC, City Code of Ordinances and any other relevant standards.

[1] Exceptions to this requirement are available where the sleeping room or living area has a door leading directly to the outside at or to the finished ground level, or where the dwelling unit is fully sprinkled.

[2] The City may allow windows to remain that are an “existing approved means of escape.” *Id.* § 24.2.2.3. An approved existing condition is “That which is already in existence on the date [the NFPA code] goes into effect and is acceptable to the authority having jurisdiction.” *Id.* § 3.3.75.1.
