## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

July 20, 2017

Responsible Party 1:				
Rosemont Properties LLC				
89 Forbes Ln				
Windham, ME 04062				
Location	CBL	<b>Inspection Date</b>		
Location 44 WHITNEY AVE	CBL 186 A021001	Inspection Date 6/23/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 8/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
<b>NFPA 101- 7.5.1.1 AND 7.5.1.1.1 OBSTRUCTED EGRESS</b> ; Exits shall be located and exit access shall be arranged so that exits are readily accesible at all times (7.5.1.1). Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4 (7.5.1.1.1).  No Storage in Back stairway.	
<b>NFPA 101- 7.5.1.1 AND 7.5.1.1.1 OBSTRUCTED EGRESS</b> ; Exits shall be located and exit access shall be arranged so that exits are readily accesible at all times (7.5.1.1). Where exits are not immediately accessible from an open floor area, continuous passageways, aisles, or corridors leading directly to every exit shall be maintained and shall be arranged to provide access for each occupant to not less than two exits by separate ways of travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4 (7.5.1.1.1).  Basement door is blocked by a half door in front of the fire door.	
NFPA 101- 4.5.3.4 MEANS OF EGRESS SHALL BE ILLUMINATED; Lighting: Where artifical illumination is needed in a building or structure, egress facilities shall be included in the lighting design.  front and rear stairways need to be lighted.	
<b>NFPA 101-40.2.4 MEANS OF EGRESS</b> ; The number of means of egress shall comply with either 40.2.4.1.1 or 40.2.3.2. Fire doors need to be installed to apts on front and rear stairs, with numbers.	

Violation		Proposed Date of Completion
an open floor area, continuous pass shall be maintained and shall be ar	CTED; Where exits are not immediately accessible from sageways, aisles, or corridors leading directly to every exit ranged to provide access for each occupant to not less travel, unless otherwise provided in 7.5.1.1.3 and 7.5.1.1.4. to basement	IMMEDIATELY remove all obstructions from the exits. Your signature below indicates that all obstructions have been removed and will not be replaced.
normally required to be kept closed	S MUST BE SELF- OR AUTO-CLOSING; A door leaf shall not be secured in the open position at any time and osing in accordance with 7.2.1.8.2, unless otherwise	//
NFPA 101-7.10.5.1 NORMAL ILLU 7.10.1.5, or 7.10.8.1, other than wh shall be suitably illuminated by a rel	JMINATION FOR EXITS; Every sign required by 7.10.1.2, ere operations or processes require low lighting levels, liable light source. Externally and internally illuminated rmal and emergency lighting mode.	//
FINAL DATE OF COMPLETED VI	OLATION(S)	//
FIRE PREVENTION BUREAU RE	INSPECTION OF COMPLETED VIOLATION(S)	//
questions.  VIOLATOR CERTIFICATION  I agree to remedy the violations understand that I must contact the is entirely within the Bureau's distributed in the second of the interval of the second of the interval of the interva	listed within the timeframes provided. If I require add the Fire Prevention Bureau <u>prior to the deadline</u> to requ iscretion to grant or deny. In y responsibility to schedule a reinspection of my prope ty failure to schedule a reinspection shall be deemed an	litional time to comply, I uest an extension, which erty once the violations n admission that the
	3 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	• •
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	