## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

May 11, 2017

Responsible Party 1:				
SULLIVAN STEPHEN				
172 BOLTON ST # 2				
PORTLAND, ME 04102				
Location	CBL	Inspection Date		
<b>Location</b> 170 BOLTON ST	CBL 186A D012001	Inspection Date 10/19/2016		
		<del>-</del>		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 5/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  Repair smoke detector 3rd floor rear stairs	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 1 EXCESSIVE/DISORDERLY STORAGE; Reference NFPA 1 for excessive fuel-load.	/ /
Rear stairwell	, ,
<b>NFPA 70 MISSING BOX COVERS</b> ; Refer to NFPA 70, National Electrical Code, on standards for missing box covers.	/
Front porch first floor ceiling, cover plate for light switch second floor landing rear stairwell	,
<b>NFPA 70 MISSING BREAKER IN PANEL</b> ; Refer to NFPA 70, National Electrical Code, for information on missing breakers in an electrical panel. First and Third floor panels	//
<b>NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED</b> ; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour.	//
Front and rear stairwells to all units, basement to rear stairwell, basement to first floor apartment	

Violation		Proposed Date of Completion
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
9	to reject or modify any proposed plan of action, and may cal capacity to complete the proposed plan. Please contaction	-
•	ns listed within the timeframes provided. If I require add t the Fire Prevention Bureau <u>prior to the deadline</u> to req s discretion to grant or deny.	1 2
	my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed a died.	
v v	reement, I understand that I am liable for penalties pursi §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	