

Permitting and Inspections Department Michael A. Russell, MS, Director

QUINLAN KEVIN D 47 STEVENS AVE PORTLAND, ME 04102

CBL: 188 A038001

Located at: 47 STEVENS AVE

Certified Mail 7015 3010 0000 0201 0815

Dear QUINLAN KEVIN D,

An evaluation of the above-referenced property on 07/29/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 09/02/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Matthew Sarapas

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager QUINLAN KEVIN D		Inspector Matthew Sarapas	Inspection Date 7/29/2017
Location 47 STEVENS AVE	CBL 188 A038001	Status Violations Exist	Inspection Type Inspection
Code	Int/Ext Floor	Unit No. Area	Compliance Date

Violation:

NFPA 101- 7.2.1.15.8 FIRE DOORS MUST BE REPAIRED OR MAINTAINED; DOOR OPENINGS

NOT IN PROPER OPERATING CONDITION SHALL BE REPAIRED OR REPLACED WITHOUT

DELAY.

Notes:

Adjust self closing hinges throughout to ensure doors close and positively latch

2) 55.05

Violation:

NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification

appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing

information to occupants or staff, shall comply with the requirements of Chapter 6.

Notes:

Hardwired carbon monoxide alarms required in common areas each level including basement. Tenants

have removed current plug in alarms.

3) 55.20

Violation:

NFPA 101- 31.3.3.2 INTERIOR FINISH; INTERIOR WALL AND CEILING FINISH MATERIALS

COMPLYING WITH 10.2 SHALL BE PERMITTED AS FOLLOWS:

(1) EXIT ENCLOSURES- CLASS A OR B

(2) LOBBIES AND CORRIDORS- CLASS A OR B

(3) OTHER SPACES- CLASS A, B, OR C.

Notes:

Unrated paneling in rear stairs must be removed or coated with intumescent paint. Carpet in front stairs

must be rated or removed.

4) 55.530

Violation:

CITY OF PORTLAND RULES AND REGS- CHAPTER 4.6 LABEL UNIT DOORS; 4.6 Commercial

suites shall be designated as approved by the FD. In single floor buildings letter designations shall be

acceptable.

4.6.1 Residential units shall be designated using numericals.

4.6.2 The first numerical of each residential unit shall be the floor designation.

4.6.3 In single floor buildings the floor designation shall be omitted.

Notes:

Number unit doors front and rear

5) 55.485

Violation:

NFPA 101-31,3.6.3.1 UNPROTECTED OPENINGS ARE PROHIBITED IN CORRIDORS;

UNPROTECTED OPENINGS, OTHER THAN THOSE FROM SPACES COMPLYING WITH

31.3.6.3.2, SHALL BE PROHIBITED IN EXIT ACCESS CORRIDOR WALLS AND DOORS.

Attic hatch and closet ceiling in rear stairway need one hour fire rating. Notes:

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager QUINLAN KEVIN D		Inspector Matthew Sarapas	Inspection Date 7/29/2017
Location	CBL	Status	Inspection Type
47 STEVENS AVE	188 A038001	Violations Exist	Inspection

6) 55.300

Violation:

NFPA 101-31.2.2.2.2.1 DOORS LOCKED AGAINST EGRESS; NO DOOR IN ANY MEANS OF

EGRESS SHALL BE LOCKED AGAINST EGRESS WHEN THE BUILDING IS OCCUPIED.

Notes: Replace deadbolt in unit #2 front with model not requiring key to operate

7) 1.155

Violation: 1-10.12.1 STREET NUMBERS ON FRONT OF BUILDING; NEW AND EXISTING BUILDINGS SHALL

HAVE APPROVED ADDRESS NUMBERS PLACED IN A POSITION TO BE PLAINLY LEGIBLE AND

VISIBLE FROM THE STREET OR ROAD FRONTING THE PROPERTY.

Notes:

8) 3.011

Violation: NFPA 101- 31.3.2.1.1 BOILER PROTECTION REQUIRED; THE AREAS DESCRIBED IN TABLE

31.3.2.1.1 SHALL BE PROTECTED AS INDICATED:

BOILER AND FUEL-FIRED HEATER ROOMS SERVING MORE THAN A SINGLE DWELLING UNIT

(MINIMUM SEPARATION/PROTECTION IS 1 HOUR OR SPRINKLERS)

Notes:

Comments: