## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

May 18, 2017

Responsible Party 1:				
FIDDLER'S GREEN LLC				
36 LIBERTY WAY				
PORTLAND, ME 04103				
Location	CBL	Inspection Date		
Location 1236 CONGRESS ST	<b>CBL</b> 189 A001001	<b>Inspection Date</b> 5/8/2017		
		-		

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 6/15/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 101- 31.3.7 FLOOR/ CEILINGS ASSEMBLY NOT SMOKE-TIGHT; In buildings other than those meeting the requirements of 31.3.7.1, 31.3.7.2, 31.3.7.3, 31.3.7.4, or 31.3.7.5, in addition to the following criteria to be met.  Ceiling breach in the lower room off the main floor area.	//
NFPA 101-7.9.3 EMERGENCY LIGHTS REQUIRE MAINTENANCE; 7.9.3 Periodic Testing of Emergency Equipment 7.9.3.1 Required emergency lighting systems shall be tested in accordance with one of the three options offered by 7.9.3.1.1, 7.9.3.1.2, or 7.9.3.1.3. 7.9.3.1.1 Testing of required emergency lighting systems shall be permitted to be conducted as follows: (1) Functional testing shall be conducted monthly with a minimum of 3 weeks and a maximum of 5 weeks between tests, for not less than 30 seconds, except as otherwise permitted by 7.9.3.1.1(2). (2) The test interval shall be permitted to be extended beyond 30 days with the approval of the authority having jurisdiction. (3) Functional testing shall be conducted annually for a minimum 1-1/2 hours if the emergency lighting system is battery powered. (4) The emergency lighting equipment shall be fully operational for the duration of the test required by 7.9.3.1.1(1) and (3). (5) Written records of visual inspections and tests shall be kept by the owner for inspection by the authority having jurisdiction.  Emergency lights at the rear exit are inoperable.	
NFPA 101- 31.2.2.1.2 EXIT STAIR REQ. 60-MIN FIRE RATING - NON-HIGH-RISE; In buildings using Option 4, exit enclosures shall have a minimum 1-hour fire resistance rating, and doors shall have a minimum 1-hour fire protection rating.  Basement stairs have no fire rating protection underneath.	//

Violation		Proposed Date of Completion
	revention.	//
FINAL DATE OF COMPLETI	ED VIOLATION(S)	//_
FIRE PREVENTION BUREA	U RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	th to reject or modify any proposed plan of action, and may unical capacity to complete the proposed plan. Please contactation	
I agree to remedy the violat understand that I must cont is entirely within the Bureau I further understand that it have been remedied to do so violations have not been remedied.	tions listed within the timeframes provided. If I require add fact the Fire Prevention Bureau prior to the deadline to requir's discretion to grant or deny.  This my responsibility to schedule a reinspection of my prope to. My failure to schedule a reinspection shall be deemed armedied.	uest an extension, which rty once the violations and admission that the
	agreement, I understand that I am liable for penalties pursures §§ 1-15 and 10-25, and 30-A M.R.S. § 4452 and may be	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	