

From: Karen Johnson <karen@chartweb.com>
To: "Jean Fraser (JF@portlandmaine.gov)" <JF@portlandmaine.gov>
Date: 6/3/2014 9:15 AM
Subject: Westgate Plaza - Congress Street Dunkin Donuts
Attachments: C-0942_SITE_REST_DRIVETHROUGH(REVISED) - Copy DRIVET.PDF

Good Morning Jean, we ran into a slight issue with the Dunkin drive through configuration as the operator was concerned about the location of the ground mounted HVAC units. Please note the minor adjustment in the attached pdf. This configuration provides for the same stacking from the menu board and the same location at the end of the queue but just shifts the menu board around the building corner. We believe this is a minor adjustment but wanted to confirm with you.

Thanks

Karen

Karen Johnson, AICP
Charter Realty & Development Corp.
800 Westchester Avenue, Suite S-632
Rye Brook, NY 10573
914 701-4002 Fax 914 701-4003

1666 Massachusetts Avenue, Suite 4
Lexington, MA 02173
617 431-1091

karen@chartweb.com<mailto:karen@chartweb.com>
www.chartweb.com
[cid:0312BF54-DE28-4A45-BE07-189F9459D361]