

Date:	11/15/2004	
Time:	4:45 PM	
Temp:	45 F	
Weather:	Dark	

Observation Report - 030 Cast-in-Place Concrete

Portland, ME			
826			
Pre placement review Slab on Grade			
To place money of the characteristics			
Satisfactory Unsatisfactory Not Completed N/A	sfactory atisfactory Completed		
Satisfactory Unsatisfactory Not Complete N/A	Satisfactory Unsatisfactory Not Completec N/A		
satis t Co	tisfa satis t Co		
	Satis Uns Not	Additional Items:	
X Reinforcement Size X Quantity			
X Condition			
X Placement X Embed/Anchors			
X Laps/ Splices			
Reinf. Weld X Hot Weather			
X Cold Weather			
Annualizately 000% of horse have been installed	at this time. Assessment the	Adhan and man ahain. Dans a	
Approximately 90% of bars have been installed contraction joints as per details.	at this time. Appears tha	it triey need more chairs. Bars ar	e cui ai
Bars were added at Y/41 as per SKST-14.			
2410 11010 444004 41 17 11 40 501 5116 1 11			
Todd M. Neal, P.E.	Date: 11	/15/2004	