



GEOTECHNICAL ▼ ENVIRONMENTAL ▼ INSPECTIONS ▼ TESTING

STRUCTURAL STEEL SITE INSPECTION

CLIENT: Old Dominion Freight Lines
500 Old Dominion Way
Thomasville, NC. 27360
Attn: Philip Danner

PROJECT: Old Dominion Building Expansion
185 Rand Road
Portland, ME

DATE: October 2, 2014

REPORT #: 14-55-00014-026A

As requested, a site visit was made on this date for inspection of structural steel framing. Upon arrival our inspector met with the contractor. Drawings were reviewed.

We began our inspection and noted loose nuts on anchor rods and gaps between faying surfaces of up to 5/16" on all rafter to column connections (faying surfaces are required to be tight).

We recommended that the erector re-visit all connections and tighten as required. Once this has been completed a return visit will be made.

Inspector; R. Allen Nason
CWI #02050551
ICC #8049937-S1