

## **REPORT OF PRE-CONCRETE REINFORCING STEEL INSPECTION**

CLIENT:	Old Dominion Freight Lines 500 Old Dominion Way Thomasville, NC. 27360 Attn: Philip Danner	PROJECT:	Old Dominion Building Expansion 185 Rand Road Portland, ME
DATE:	August 18, 2014	<b>REPORT #:</b>	14-55-00014-005

On site to inspect the Reinforcing Steel for locations listed below. Unless noted otherwise, all reinforcing steel is in accordance with the approved set of drawings, specifications and applicable codes.

## Location: Starting in-between 13-14 and 15 on far side

Proper Size:	Yes	No		Anchor Bolts Placed:	Yes	No	N/A
Proper Grade:	Yes	No		Proper Spacing:	Yes	No	
Proper Quantity:	Yes	No		Proper Clearance:	Yes	No	
Masonry/Wall Dowels:	Yes	No	N/A	Proper Lap Splice:	Yes	No	N/A
Embeds Placed:	Yes	No	N/A	Area of Placement fre & clear of debris:	e (Yes)	No	

Drawing Detail: <u>S3.1</u>

Shop Drawing Detail: <u>3 A-2 @ 10"</u>

\*Remarks:

Ernie Kraytenberg Inspector/Technician John Turner Consulting, Inc.

□ Non Compliant

✓ Compliant

Remarks

□ Fix

NH MA ME CT VT RI

## JOHN TURNER CONSULTING

19 DOVER STREET DOVER, NH 03820 T 603.749.1841 F 603.516.6851 66 SOUTHGATE STREET WORCESTER MA 01603 **T** 508.505.0126 6 CLINTON AVENUE WESTFIELD MA 01085 T 413.642.0138 4775 ROUTE 14, UNIT 3 WRJ, VT 05001 T 802.295.1100 73 RAINMAKER DRIVE Portland ME 04103-1291 T 207.883.7878

**CONSULTJTC.COM**