



## REPORT OF PRE-CONCRETE REINFORCING STEEL INSPECTION

**CLIENT:** Old Dominion Freight Lines  
500 Old Dominion Way  
Thomasville, NC. 27360  
Attn: Philip Danner

**PROJECT:** Old Dominion Building Expansion  
185 Rand Road  
Portland, ME

**DATE:** August 19, 2014

**REPORT #:** 14-55-00014-006

On site to inspect the Reinforcing Steel for locations listed below. Unless noted otherwise, all reinforcing steel is in accordance with the approved set of drawings, specifications and applicable codes.

**Location:** Starting on 15-10

|                             |                                      |                          |                                      |  |                                      |                          |                                      |
|-----------------------------|--------------------------------------|--------------------------|--------------------------------------|--|--------------------------------------|--------------------------|--------------------------------------|
| <b>Proper Size:</b>         | <input checked="" type="radio"/> Yes | <input type="radio"/> No |                                      | <b>Anchor Bolts Placed:</b>                          | <input type="radio"/> Yes            | <input type="radio"/> No | <input checked="" type="radio"/> N/A |
| <b>Proper Grade:</b>        | <input checked="" type="radio"/> Yes | <input type="radio"/> No |                                      | <b>Proper Spacing:</b>                               | <input checked="" type="radio"/> Yes | <input type="radio"/> No |                                      |
| <b>Proper Quantity:</b>     | <input checked="" type="radio"/> Yes | <input type="radio"/> No |                                      | <b>Proper Clearance:</b>                             | <input checked="" type="radio"/> Yes | <input type="radio"/> No |                                      |
| <b>Masonry/Wall Dowels:</b> | <input checked="" type="radio"/> Yes | <input type="radio"/> No | N/A                                  | <b>Proper Lap Splice:</b>                            | <input checked="" type="radio"/> Yes | <input type="radio"/> No | N/A                                  |
| <b>Embeds Placed:</b>       | <input type="radio"/> Yes            | <input type="radio"/> No | <input checked="" type="radio"/> N/A | <b>Area of Placement free &amp; clear of debris:</b> | <input checked="" type="radio"/> Yes | <input type="radio"/> No |                                      |

**Drawing Detail:** S3.1

**Shop Drawing Detail:** 3 A.2 @ 15-10

**\*Remarks:** Switched Stirrups out for the correct size

Ernie Kraytenberg  
**Inspector/Technician**  
**John Turner Consulting, Inc.**

Non Compliant

Compliant

Remarks

Fix

**NH MA ME CT VT RI**

**JOHN TURNER CONSULTING**

**CONSULTJTC.COM**

19 DOVER STREET  
DOVER, NH 03820  
T 603.749.1841 F 603.516.6851

66 SOUTHGATE STREET  
WORCESTER MA 01603  
T 508.505.0126

6 CLINTON AVENUE  
WESTFIELD MA 01085  
T 413.642.0138

4775 ROUTE 14, UNIT 3  
WRJ, VT 05001  
T 802.295.1100

73 RAINMAKER DRIVE  
PORTLAND ME 04103-1291  
T 207.883.7878