



REPORT OF PRE-CONCRETE REINFORCING STEEL INSPECTION

CLIENT: Old Dominion Freight Lines 500 Old Dominion Way Thomasville, NC. 27360 Attn: Philip Danner	PROJECT: Old Dominion Building Expansion 185 Rand Road Portland, ME
DATE: September 10, 2014	REPORT #: 14-55-00014-014

On site to inspect the Reinforcing Steel for locations listed below. Unless noted otherwise, all reinforcing steel is in accordance with the approved set of drawings, specifications and applicable codes.

Location: Slab on grade, 10-16 on A-B

Proper Size:	<input checked="" type="radio"/> Yes	<input type="radio"/> No		Anchor Bolts Placed:	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A
Proper Grade:	<input checked="" type="radio"/> Yes	<input type="radio"/> No		Proper Spacing:	<input checked="" type="radio"/> Yes	<input type="radio"/> No	
Proper Quantity:	<input checked="" type="radio"/> Yes	<input type="radio"/> No		Proper Clearance:	<input checked="" type="radio"/> Yes	<input type="radio"/> No	
Masonry/Wall Dowels:	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A	Proper Lap Splice:	<input checked="" type="radio"/> Yes	<input type="radio"/> No	<input type="radio"/> N/A
Embeds Placed:	<input type="radio"/> Yes	<input type="radio"/> No	<input checked="" type="radio"/> N/A	Area of Placement free & clear of debris:	<input checked="" type="radio"/> Yes	<input type="radio"/> No	

Drawing Detail: 5/S3.1

Shop Drawing Detail:

***Remarks:**

Tristan Brackett
Inspector/Technician
John Turner Consulting, Inc.

Non Compliant

Compliant

Remarks

Fix

NH MA ME CT VT RI

JOHN TURNER CONSULTING

CONSULTJTC.COM

19 DOVER STREET
 DOVER, NH 03820
 T 603.749.1841 F 603.516.6851

66 SOUTHGATE STREET
 WORCESTER MA 01603
 T 508.505.0126

6 CLINTON AVENUE
 WESTFIELD MA 01085
 T 413.642.0138

4775 ROUTE 14, UNIT 3
 WRJ, VT 05001
 T 802.295.1100

73 RAINMAKER DRIVE
 PORTLAND ME 04103-1291
 T 207.883.7878