

8709 Line Isolator Module for Use With MPC-6000 & 7000 Control Panels

Features

- Short Circuit Isolation
- Used on MPC-6000 & 7000 Intelligent Device Circuits
- Increased FaultTolerance
- Style 4 or Style 6
- Up to 12 Per Loop
- Requires no Programming
- Does Not Occupy a Device Address
- Mounts in Either 4" Square, 21/8" Deep or a 3 1/2" Deep Double Gang Electrical Box
- Local LED Indicator
- Cover Plate Included
- (UL) Listed, NYMEA and CSFM Submitted



Description

The 8709 loop isolator module provides short circuit protection on MPC-6000 & 7000 intelligent device circuits (FDLC). When a short is detected by the 8709, it isolates the affected segment of the circuit, allowing the remaining devices to continue operation. The 8709 is self-restoring, automatically reconnecting to circuit segment when the fault is removed.

The 8709 also includes a yellow LED which illuminates to indicate that the device has been activated. The 8709 mounts in either a 4" square, 2 1/8" deep or a 3 1/2" deep double gang electrical box and is supplied with a cover plate with an opening for the LED.

It can be wired in either a Style 4 or Style 6 configuration.

The 8709 does not occupy a device address on the intelligent device circuit and requires no programming. Up to twelve 8709s may be installed on each loop.

Ordering Information

Model	Description	Part No.
8709	Line Isolator Module	500-033170FA



Siemens Building Technologies, Inc. 8 Fernwood Road • Florham Park, NJ 07932 Tel: (973) 593-2600 • Fax: (973) 593-6670 Web: www.faradayfirealarms.com WARNING - The information contained in this document is intended only as a summary and is subject to change without notice. The devices described in this document have specific instruction sheets which cover various technical, limitation and liability information. Copies of these instruction sheets and the General Product Warning and Limitations Document, which also contains important information, are provided with the product and are available from the Manufacturer. Information contained in these documents should be consulted before specifying or using the product. For further information or assistance concerning particular problems contact the Manufacturer.