

the architectural team

The Architectural Team, Inc. 50 Commandant's Way at Admiral's Hill www.architecturalteam.com



November 25, 2015

Sheet Number:

REPOINT MORTAR JOINTS. REFER TO SPECIFICATIONS.

REMOVE DAMAGED BRICK. REFER TO SPECIFICATIONS.

15. REMOVE EXISTING ALUMINUM COPING.

REMOVE EXISTING TRASH CHUTE VENT.

SHEATHING.

14. REMOVE DAMAGED SLATE SHINGLE SIDING AT ROOF DORMERS.

REMOVE EXISTING ASPHALT SHINGLE ROOFING SYSTEM TO ROOF

1 5 10