



— ROTTED LEDGER BOARD
TO BE REPLACED AND
PROPERLY FASTENED.