

## Permitting and Inspections Department Michael A. Russell, MS, Director

December 2, 2017

LAIRD DIANA 21 CUMBERLAND ST # 4 BOSTON, MA 02115

CBL: 298 A042001

Located at: 17 W COMMONWEALTH DR

Certified Mail 70132250000169951588

Dear LAIRD DIANA,

An evaluation of the above-referenced property on 11/22/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 01/05/2018 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

Kevin Hanscombe

Code Enforcement Officer

## CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

## **Inspection Violations**

Owner/Manager LAIRD DIANA		Inspector Kevin Hanscombe	Inspection Date 11/22/2017
Location	CBL	Status	Inspection Type
17 W COMMONWEALTH	298 A042001	Violations Exist	Housing Safety Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 206

Violation: SMOKE ALARMS / BEDROOMS; Smoke Alarms - One and Two-Family Dwellings: Single-station or

multiple-station (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or

ceilings: in all sleeping rooms.

NFPA 101 (2009) 24.3.4.1(1), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes: All bedrooms need smoke alarms

2) 207

Violation: CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings:

Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on

walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes: CO alarms are required on every level of the property including basements and preferably located in

the common area outside the bedrooms. (we allow the use of combination smoke and co alarms where

applicable)

3) 210

Violation: ESCAPE WINDOWS: Escape Windows - One and Two-Family Dwellings: Escape windows shall be a

free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with

an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes: The 2 bedrooms upstairs did not have the required measurments for egress (emergency

escape/rescue)

Comments: Detection requirements must be addressed immediately and a reinspection performed by 01/05/2018.

During the reinspection a plan of actions to address the egress windows will be required.