Yes. Life's good here.

Planning & Urban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

November 24, 2015

AL AHRAM LLC 630 FOREST AVE PORTLAND, ME 04101

CBL: 344 C004001

Certified Mail 7010 1870 0002 8136 9562

Located at: 1344 WASHINGTON AVE

Dear Mr. Ahram,

SECOND NOTICE OF VIOLATION

An evaluation of the above-referenced property on 11/24/2015 revealed that the structure remains non-compliant with the Housing Code of the City of Portland.

Attached is a list of the violations.

This is a **SECOND** notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected. A re-inspection will occur on 12/08/2015, at which time compliance will be required.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A M.R.S.A ss 4452.

Please feel free to contact me is you wish to discuss this matter further or have any questions.

Sincerely

Chuck Fagone

Code Enforcement Officer

(207) 874-8789

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date 11/24/2015	
Al Ahram Llc		Chuck Fagone		
Location	CBL	Status	Inspection Type	
1344 WASHINGTON AVE	344 C004001	Re-Inspect 14 Days	Complaint-Infestation/Insects	

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date

1) 22.3.3(a)

Exterior

Yard

Violation:

PREMISES TO BE KEPT FREE FROM RODENT HARBORAGE

The owner of a two (2) or more family residential building and the owner or occupant of a single family residential building shall maintain the building and the lot on which the building is located free from any accumulation of any putrid substance, garbage, rubbish, old lumber, debris or rubble,

except in watertight covered containers.

Notes:

Furniture debris and appliances (stove) will need to be removed or an addition \$150 re-inspection fee

will be assessed.