

Permitting and Inspections Department Michael A. Russell, MS, Director

October 26, 7014

BOUWENS DONALD M & 47 SAUNDERS ST PORTLAND, ME 04103

CBL: 344 G030001

Located at: 15 CYPRESS ST

Certified Mail 7014 1820 0001 4049 6911

Dear BOUWENS DONALD M &,

An evaluation of the above-referenced property on 10/25/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 9 days of the date of this notice. A re-inspection of the premises will occur on 11/03/2017 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Jason Duval

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager BOUWENS DONALD M &		Inspector Jason Duval	Inspection Date 10/25/2017
Location	CBL	Status	Inspection Type
15 CYPRESS ST	344 G030001	Failed	Housing Safety Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 207

Violation: CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings:

Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on

walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes: Basement is required to have CO alarm.

Comments: CO alarm missing in basement.