

Permitting and Inspections Department Michael A. Russell, MS, Director

February 27, 2018

CURTIS LAWRENCE L ETAL 11 MERRILL DR HARRISON, ME 04040

CBL: 347 B035001

Certified Mail 70150920000107766591

Located at: 104 HENNESSY DR

Dear CURTIS LAWRENCE LETAL,

This is a **SECOND NOTICE!** An evaluation of the above-referenced property on 11/17/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected immediately and a re-inspection of the premises must occur or before on or before **05/08/2018** at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection. Sincerely,

Kevin Hanscombe

/s/

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager CURTIS LAWRENCE L ETAL		Inspector Kevin Hanscombe	Inspection Date 11/17/2017
104 HENNESSY DR	347 B035001	Violations Exist	Housing Safety Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 210

Violation:

ESCAPE WINDOWS; Escape Windows - One and Two-Family Dwellings: Escape windows shall be a free and clear outside window or door operable from the inside without the use of tools, keys, or special effort. Windows shall be within 20 feet of the finished ground level or accessible by rescue apparatus (if approved), or opening onto an exterior balcony and when below ground level shall be provided with an accessible, free and clear, window well.

NFPA 101 (2009) 24.2.2.3.3

Notes:

bedroom windows

Comments: