

Permitting and Inspections Department Michael A. Russell, MS, Director

November 14, 2017

CARON ROBERT J & 11 CORNERSTONE DR FALMOUTH, ME 04105

CBL: 352 C017001

Certified Mail 7014 1820 0001 4049 7116

Located at: 289 PALMER AVE

Dear CARON ROBERT J &,

An evaluation of the above-referenced property on 11/14/2017 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 14 days of the date of this notice. To schedule a re-inspection please contact Housing Safety at 207-756-8131 or email housingsafety@portlandmaine.gov within 14 days.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely,

/s/

Jason Duval

Code Enforcement Officer

CITY OF PORTLAND HOUSING SAFETY OFFICE

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager CARON ROBERT J &		Inspector Jason Duval	Inspection Date 11/14/2017
289 PALMER AVE	352 C017001	Failed	Housing Safety Inspection

Code Int/Ext Floor Unit No. Area Compliance Date

1) 206

Violation: SMOKE ALARMS / BEDROOMS; Smoke Alarms - One and Two-Family Dwellings: Single-station or

multiple-station (interconnected) photoelectric smoke alarms must be powered by the building electrical system or powered by a 10-year non-replaceable battery and shall be positioned correctly on walls or

ceilings: in all sleeping rooms.

NFPA 101 (2009) 24.3.4.1(1), 9.6.2.10, amended by City Code of Ordinances Section 10-3(i)

Notes: Bedrooms require smoke alarms.

2) 207

Violation: CARBON MONOXIDE ALARMS / LEVEL; Carbon Monoxide Alarms - One and Two-Family Dwellings:

Single-station or multiple-station (interconnected) Carbon Monoxide alarms must be powered by the (A) building electrical system, or (B) 10-year non-replaceable battery and shall be positioned correctly on

walls or ceilings: (1) on each level of the dwelling unit, and (2) including the basement.

NFPA 720 (2009) 9.5.1, 9.5.3, amended by State Law Title 25, Chapter 317 § 2468

Notes: CO alarm required for 2nd floor and basement.

Comments: All bedrooms need smoke alarms. CO alarm needed on 2nd floor and basement.