

City of Portland, Maine
Inspections Division
Violations Report
Appointment Date - 4/14/2016

Dist. #	Sch. Date	CBL	Appl. Type	Schedule Type	Appl #	Location
	Contact:		Inspector	Comments		
5	04/14/2016	373 B005001	Fire Company	FP Routine Inspection		238 AUBURN ST Building F
	BROOKFIELD PROPERTY		Michael Scherb			

Code	Violation	Status	IntExt	Floor	Area	Corrected	Date
NFPA 101-7.1.10.2.1-7.008	Debris Inside Building Tennants storing baby carriage in hallway	Open	Interior	2	Hallway	<input type="checkbox"/>	
NFPA 101-7.1.10.2.1-7.008	Debris Inside Building Grill stored in hallway	Open	Interior	Basement	Hallway	<input type="checkbox"/>	

Dist. #	Sch. Date	CBL	Appl. Type	Schedule Type	Appl #	Location
	Contact:		Inspector	Comments		
5	04/14/2016	373 B005001	Fire Company	FP Routine Inspection		238 AUBURN ST Building E
	BROOKFIELD PROPERTY		Michael Scherb			

Code	Violation	Status	IntExt	Floor	Area	Corrected	Date
NFPA 101-7.2.1.8.1-9.006	Fire Door(s) Must Self-close Hallway fire door outside laundry room does not self close	Open	Interior	Basement	Hallway	<input type="checkbox"/>	

Dist. #	Sch. Date	CBL	Appl. Type	Schedule Type	Appl #	Location
	Contact:		Inspector	Comments		
5	04/14/2016	373 B005001	Fire Company	FP Routine Inspection		238 AUBURN ST Building C
	BROOKFIELD PROPERTY		Michael Scherb			

Code	Violation	Status	IntExt	Floor	Area	Corrected	Date
NFPA 101-8.3.5-2.120	Hole In Wall Needs Repair Hole in drywall in Laundry room	Open	Interior	Basement	Laundry Roo	<input type="checkbox"/>	
NFPA 101-8.3.5-2.120	Hole In Wall Needs Repair Access under stairway needed to be covered	Open	Interior	Basement	Hallway	<input type="checkbox"/>	

Dist. #	Sch. Date	CBL	Appl. Type	Schedule Type	Appl #	Location
	Contact:		Inspector	Comments		
5	04/14/2016	373 B005001	Fire Company	FP Routine Inspection		238 AUBURN ST Building B
	BROOKFIELD PROPERTY		Michael Scherb			

Code	Violation	Status	IntExt	Floor	Area	Corrected	Date
NFPA 70-4.10.8-6.005	Defective Light Fixture Hanging light in one of the storage units in Laundry room	Open	Interior	Laundry	Basement	<input type="checkbox"/>	
NFPA 101-8.3.5-2.120	Hole In Wall Needs Repair Holes in wall in the 3rd floor landing	Open	Interior	3	Hallway	<input type="checkbox"/>	
NFPA 101-8.3.5-2.120	Hole In Wall Needs Repair Access under stairwell needs to be covered up	Open	Interior	basement	Basement	<input type="checkbox"/>	
NFPA 101-7.2.1.8.1-9.006	Fire Door(s) Must Self-close Self closer on 3rd floor fire door is broken	Open		3	Hallway	<input type="checkbox"/>	

Dist. #	Sch. Date	CBL	Appl. Type	Schedule Type	Appl #	Location
	Contact:		Inspector	Comments		
5	04/14/2016	373 B005001	Fire Company	FP Routine Inspection		238 AUBURN ST Building A
	BROOKFIELD PROPERTY		Michael Scherb			

Code	Violation	Status	IntExt	Floor	Area	Corrected	Date
NFPA 101-8.3.5-2.120	Hole In Wall Needs Repair Access hole under stairway needs to be closed off	Open	Interior		Hallway	<input type="checkbox"/>	