

50
Portland ME

Remaining part of
the Framing
Sill's
and
Nail
with

--	--	--	--	--	--	--	--	--	--

Remaining
12
Do to
fire
damage
trusses