

9/12/01 Footing setback inspection revealed inconsistencies with submitted plans - Hole was dug w/ surveyed pins but w/ daylight basement in rear. All setbacks were met according to plan submitted. Will need to Ammend plans to show changes. Stop work order issued until new permit approved. No pouring of concrete allowed. JB

See notes
New notes
on amended
permit

01-1184
and permit # 00-0775