

Found boiler cracked leaking water into
chamber on 3-7-14 changed boiler
on 3-11-14.

Boiler vented into a brick chimney
lined with a stainless liner.