

9/13/01 Close ^{PERMIT} inspection = Requested Specs on
Steel Beam in garage. Garage ceiling joists need
gusset to connect butt joint. Need #8 ~~Bedding~~ Wire
to spa motor, Exterior stairs needs solid risers or
less than 4", need Graspable Hand Rail, Top step is 1/2"
greater than previous, some balusters < 4" space
OK to close - everything accessible JB

11/15/01 - Got spec on Beam - garage ceiling joists had
gussets attached to Butt joint. #8 wire added to spa motor.
Exterior Stairs are conforming all above items taken
care of. Close out permitst, CBL# 397-D-15
permitst 01-0386