Client	Hawthorn
Project	Portland, ME
Lead Designer	
<b>Production Manager</b>	Jason DiOrazio
Production Staff	

Revision #	Sheet	Description of Change	A0.0 Dotted?	Assigned Date	Responsible Staff	Completion Date
5	A0.0	Added revision 5 to title block, total area increased in square footage summary and code	Υ			8/26/2016
5	A0.1	Rear foyer increased in size, patio between Staff room and Private dining got larger	Υ			8/26/2016
5	A0.3	Added draftstop note at lower roofs	Υ			8/26/2016
5	A0.4	Added draftstop note at lower roofs	Υ			8/26/2016
5	A0.5	Rear foyer increased in size, total building area increased in code summary	Υ			8/26/2016
5	A1.1	Rear foyer increased in size	Υ			8/26/2016
5	A1.3a	Rear foyer and Can Wash areas revised	Υ			8/26/2016
5	A1.9	Hawthorn heart from detail 5 removed. Detail 7 removed	Υ			8/26/2016
5	A2.1	Rear foyer increased in size. Office/Can Wash area updated	Υ			8/26/2016
5	A2.2	Laundry rooms 257 and 263 modified	Υ			8/26/2016
5	A2.3	Laundry rooms 356 and 362 modified	Υ			8/26/2016
5	A2.4	Laundry rooms 454 and 460 modified	Υ			8/26/2016
5	A2.5	Detail callouts added/revised at atrium roof	Υ			8/26/2016
5	A2.6	Draftstop notes added at lower roofs	Υ			8/26/2016
5	A3.1	Rear foyer area increased in size, Office/Can Wash area modified, Staff/Kitchen area updated, 2x10 walls	Υ			8/26/2016
		added at the front foyer and additional mailboxes have been added to the Lounge area				
5	A3.2	Time rating added to all mechanical chase callouts	Υ			8/26/2016
5	A3.3	Time rating added to all mechanical chase callouts, soffit line removed near exterior door 181b	Υ			8/26/2016
5	A3.4	Time rating added to all mechanical chase callouts, detail 7/A8.1 added at elevator shaft	Υ			8/26/2016
5	A3.5	Time rating added to all mechanical chase callouts	Υ			8/26/2016
5	A3.6	Time rating added to all mechanical chase callouts, soffit line removed in corridor next to Storage 265	Υ			8/26/2016
5	A3.7	Time rating added to all mechanical chase callouts, detail 7/A8.1 added at elevator shaft, ice and water shield	Υ			8/26/2016
		callout added at front face of building, door 354b added to Exercise room				
5	A3.8	Time rating added to all mechanical chase callouts, draftstopping note added at lower roofs	Υ			8/26/2016
5	A3.9	Time rating added to all mechanical chase callouts, soffit line removed in corridor next to Storage 364, draftstop	Υ			8/26/2016
		note added at lower roofs				
5	A3.10	Time rating added to all mechanical chase callouts, detail 7/A8.1 added at elevator shaft	Υ			8/26/2016
5	A3.11	Time rating added to all mechanical chase callouts, draftstopping note added at lower roofs	Υ			8/26/2016
5	A3.12	Time rating added to all mechanical chase callouts, draftstopping note added at lower roofs	Υ			8/26/2016
5	A4.0	Hawthorn heart removed from detail 1	Υ			8/26/2016
5	A4.1	Office 151 revised to hard lid ceiling, soffit removed in corridor, rear foyer increased in size, soffit added	Υ			8/26/2016
		between kitchen and staff room, control joints added in dining area				
5	A4.2	Control joints added above dining area, soffit removed in corridor	Υ			8/26/2016
5	A4.3	Soffit removed in corridor, added soffits in B7 unit 339	Υ			8/26/2016
5	A4.4	Soffit removed in corridor	Υ			8/26/2016
5	A4.5	Soffits removed in corridor - all floors	Υ			8/26/2016
5	A4.6	Soffits revised at corridor "turn" at floors 1-3, soffits removed in corridor all floors	Υ			8/26/2016
5	A4.7	Soffits in Private Dining revied	Υ			8/26/2016
5	A5.1	Added key boxes at Office, louvered door added to Co-Manager unit, time rating/clarification added at all	Υ			8/26/2016
		mechanical case callouts, louvered door added to Laundy room				

5 A5.4 5 A5.5 5 A5.7 5 A5.8 5 A5.9 5 A6.0 6 A6.0 6 A6.2 6 A6.3 6 A6.3 6 A6.3 6 A6.3 6 A6.3 6 A6.4 6 A6.5 7 A6.5 7 A7.1 7 A7.2 7 A7.2 7 A7.2 7 A7.2 7 A7.3 7 A7.3 7 A7.4 7 A7.3 7 A8.0 7 A8.0 7 A8.1 7 A8.2 7 A8.3 7 A8.3 7 A8.3	Specification added to interior shutter in B2 unit, layout of B3 unit modified Layout of B17 unit updated Specification added to interior shutter in B22 unit, layout of B23 unit modified Layout of B27 unit updated, specification added to interior shutter in BD1 unit Foam insulation added to floor joist at exterior wall, ice and water shield noted added, soffit added for sprinkler line at front porch area Soffit added for sprinkler line at front porch area in sections "C" and "E" Section "X" added to sheet Can wash/Staff area modified Window lowered behind Activity room in elevation "B", added lower roof in elevation "C" Lower roof added to elevation "F" Details 6 and 13 modified to include soffit for sprinkler line at front porch area Detail 19 added to sheet, callout to detail 19 added to detail 4 Assemblies B1 and B2 added to sheet, finish information added to assembly C6 Can Section "A" and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15 Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016
5 A5.7 5 A5.8 5 A5.9 5 A6.0 5 A6.0 5 A6.2 5 A6.3 5 A6.3 5 A6.3 5 A6.3 5 A6.4 5 A6.5 5 A7.1 5 A7.1 5 A7.2 5 A7.2 5 A7.4 5 A8.0 5 A8.0 5 A8.1 5 A8.2 5 A8.3 5 A8.3	Layout of B17 unit updated Specificaion added to interior shutter in B22 unit, layout of B23 unit modified Layout of B27 unit updated, specification added to interior shutter in BD1 unit Foam insulation added to floor joist at exterior wall, ice and water shield noted added, soffit added for sprinkler line at front porch area Soffit added for sprinkler line at front porch area in sections "C" and "E" Section "X" added to sheet Can wash/Staff area modified Window lowered behind Activity room in elevation "B", added lower roof in elevation "C" Lower roof added to elevation "F" Details 6 and 13 modified to include soffit for sprinkler line at front porch area Detail 19 added to sheet, callout to detail 19 added to detail 4  Assemblies B1 and B2 added to sheet, finish information added to assembly C6 Assemblies E, F and G3 revised Clarification for TPO roofing added to detail 12 Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15 Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A5.8 5 A5.9 5 A6.0 5 A6.0 5 A6.2 5 A6.3 5 A6.3 5 A6.3 5 A6.4 5 A6.5 5 A7.1 5 A7.1 5 A7.2 5 A7.2 5 A7.4 5 A7.5 5 A8.0 5 A8.0 5 A8.1 5 A8.2 5 A8.3 5 A8.3	Specification added to interior shutter in B22 unit, layout of B23 unit modified Layout of B27 unit updated, specification added to interior shutter in BD1 unit Foam insulation added to floor joist at exterior wall, ice and water shield noted added, soffit added for sprinkler line at front porch area Soffit added for sprinkler line at front porch area in sections "C" and "E" Section "X" added to sheet Can wash/Staff area modified Window lowered behind Activity room in elevation "B", added lower roof in elevation "C" Lower roof added to elevation "F" Details 6 and 13 modified to include soffit for sprinkler line at front porch area Detail 19 added to sheet, callout to detail 19 added to detail 4 La Assemblies B1 and B2 added to sheet, finish information added to assembly C6 Lb Assemblies E, F and G3 revised Clarification for TPO roofing added to detail 12 Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15 Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A5.9 5 A6.0 5 A6.0 5 A6.2 5 A6.3 5 A6.3 5 A6.3 5 A6.3 5 A6.4 5 A6.5 5 A7.1 5 A7.1 5 A7.2 5 A7.2 5 A7.4 5 A8.0 5 A8.0 5 A8.1 5 A8.2 5 A8.2 5 A8.3 5 A8.3	Layout of B27 unit updated, specification added to interior shutter in BD1 unit  Foam insulation added to floor joist at exterior wall, ice and water shield noted added, soffit added for sprinkler line at front porch area  Soffit added for sprinkler line at front porch area in sections "C" and "E"  Section "X" added to sheet  Can wash/Staff area modified  Window lowered behind Activity room in elevation "B", added lower roof in elevation "C"  Lower roof added to elevation "F"  Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Lower specification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y  Y  Y  Y  Y  Y  Y  Y  Y  Y  Y  Y  Y	8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016
5 A6.00 5 A6.00 5 A6.20 5 A6.30 5 A6.30 5 A6.30 5 A6.30 5 A6.40 5 A6.40 5 A7.10 5 A7.10 5 A7.20 5 A7.40 5 A7.40 5 A8.00 5 A8.00 5 A8.10 5 A8.20 5 A8.20 5 A8.30	Foam insulation added to floor joist at exterior wall, ice and water shield noted added, soffit added for sprinkler line at front porch area  Soffit added for sprinkler line at front porch area in sections "C" and "E"  Section "X" added to sheet  Can wash/Staff area modified  Window lowered behind Activity room in elevation "B", added lower roof in elevation "C"  Lower roof added to elevation "F"  Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Lower sprinkler line at front porch area  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016  8/26/2016
5 A6.0 5 A6.2 5 A6.3 5 A6.3 5 A6.3 5 A6.4 5 A6.5 5 A7.1 5 A7.1 5 A7.2 5 A7.2 5 A7.2 5 A7.4 5 A8.0 5 A8.0 5 A8.1 5 A8.2 5 A8.3 5 A8.3	line at front porch area  Soffit added for sprinkler line at front porch area in sections "C" and "E"  Section "X" added to sheet  Can wash/Staff area modified  Window lowered behind Activity room in elevation "B", added lower roof in elevation "C"  Lower roof added to elevation "F"  Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A6.20 5 A6.31 5 A6.33 5 A6.33 5 A6.34 5 A6.45 5 A7.11 5 A7.20 5 A7.20 5 A7.40 5 A7.50 5 A8.00 5 A8.01 5 A8.12 5 A8.21 5 A8.21 5 A8.31 5 A8.31 5 A8.31 5 A8.31	Soffit added for sprinkler line at front porch area in sections "C" and "E"  Section "X" added to sheet  Can wash/Staff area modified  Window lowered behind Activity room in elevation "B", added lower roof in elevation "C"  Lower roof added to elevation "F"  Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  La Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Lb Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A6.20 5 A6.31 5 A6.33 5 A6.33 5 A6.34 5 A6.45 5 A7.11 5 A7.20 5 A7.20 5 A7.40 5 A7.50 5 A8.00 5 A8.01 5 A8.12 5 A8.21 5 A8.21 5 A8.31 5 A8.31 5 A8.31 5 A8.31	Section "X" added to sheet  Can wash/Staff area modified  Window lowered behind Activity room in elevation "B", added lower roof in elevation "C"  Lower roof added to elevation "F"  Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A6.3a 5 A6.3a 5 A6.3a 5 A6.3a 5 A6.4 5 A6.5 5 A7.1a 5 A7.1a 5 A7.2a 5 A7.2a 5 A7.2a 5 A7.2a 5 A7.2a 5 A8.0a 5 A8.0a 5 A8.1a 5 A8.2a 5 A8.2a 5 A8.3a 5 A8.3a 5 A8.3a	Can wash/Staff area modified  Window lowered behind Activity room in elevation "B", added lower roof in elevation "C"  Lower roof added to elevation "F"  Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  La Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Lb Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A6.3l 5 A6.3c 5 A6.4 5 A6.5 5 A7.1i 5 A7.2i 5 A7.2i 5 A7.4 5 A7.5 5 A8.0i 5 A8.1 5 A8.2i 5 A8.3i 5 A8.3i 5 A8.4i	Window lowered behind Activity room in elevation "B", added lower roof in elevation "C"  Lower roof added to elevation "F"  Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  La Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Lb Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A6.36 5 A6.4 5 A6.5 5 A7.11 5 A7.26 5 A7.26 5 A7.4 5 A7.5 5 A8.06 5 A8.06 5 A8.1 5 A8.26 5 A8.26 5 A8.36 5 A8.36 5 A8.36	Lower roof added to elevation "F"  Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  La Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Lb Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A6.4 5 A6.5 5 A7.1 5 A7.1 5 A7.2 5 A7.2 5 A7.4 5 A7.5 5 A8.0 5 A8.0 5 A8.1 5 A8.2 5 A8.2 5 A8.3 5 A8.3	Details 6 and 13 modified to include soffit for sprinkler line at front porch area  Detail 19 added to sheet, callout to detail 19 added to detail 4  Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A6.5 5 A7.1 5 A7.1 5 A7.2 5 A7.2 5 A7.4 5 A7.5 5 A8.0 5 A8.0 5 A8.1 5 A8.2 5 A8.3 5 A8.3 5 A8.3	Detail 19 added to sheet, callout to detail 19 added to detail 4  Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A7.13 5 A7.11 5 A7.23 5 A7.24 5 A7.4 5 A7.4 5 A7.5 5 A8.03 5 A8.12 5 A8.21 5 A8.33 5 A8.31 5 A8.31 5 A8.31	Assemblies B1 and B2 added to sheet, finish information added to assembly C6  Assemblies E, F and G3 revised  Clarification for TPO roofing added to detail 12  Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y Y Y	8/26/2016 8/26/2016 8/26/2016 8/26/2016
5 A7.11 5 A7.26 5 A7.26 5 A7.4 5 A7.4 5 A8.06 5 A8.06 5 A8.1 5 A8.26 5 A8.36 5 A8.36 5 A8.36 5 A8.36 5 A8.36 5 A8.36	Assemblies E, F and G3 revised Clarification for TPO roofing added to detail 12 Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15 Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y Y Y	8/26/2016 8/26/2016 8/26/2016
5 A7.26 5 A7.26 5 A7.4 5 A7.5 5 A8.06 5 A8.10 5 A8.26 5 A8.26 5 A8.36 5 A8.36 5 A8.36 5 A8.36	Clarification for TPO roofing added to detail 12 Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15 Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y	8/26/2016 8/26/2016
5 A7.20 5 A7.4 5 A7.4 5 A7.5 5 A8.00 5 A8.1 5 A8.20 5 A8.20 5 A8.30 5 A8.30 5 A8.30 5 A8.30 5 A8.30	Details 1, 2 and 4 removed from sheet. Details 3, 6, 7, 8, 9, 10 and 11 added to sheet  Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2	Y	8/26/2016
5 A7.4  5 A7.5  5 A8.0  5 A8.0  5 A8.1  5 A8.2  5 A8.3  5 A8.3  5 A8.3	Reference to standpipe detail 10/A8.8 added to detail 5, detail 6 added to sheet, ceiling assembly callout revised at details 9 and 15 Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2		
5 A8.0i 5 A8.0i 5 A8.1i 5 A8.2i 5 A8.2i 5 A8.3i 5 A8.3i 5 A8.4i	revised at details 9 and 15  Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2		0,20,2010
5 A8.0a 5 A8.0a 5 A8.1a 5 A8.2a 5 A8.2a 5 A8.3a 5 A8.3a 5 A8.4a	Unistrut layout, horizontal chase construction revised in detail 5. Note added to detail 5. Detail 6 added to sheet, reference to detail 6 added to detail 2		1, 1, 122
5 A8.0a 5 A8.0a 5 A8.1a 5 A8.2a 5 A8.2a 5 A8.3a 5 A8.3a 5 A8.4a	sheet, reference to detail 6 added to detail 2	· · · · · · · · · · · · · · · · · · ·	8/26/2016
5 A8.0l 5 A8.1 5 A8.2i 5 A8.2i 5 A8.3i 5 A8.3i 5 A8.4i	·	<del>'</del>	0,20,2010
5 A8.0l 5 A8.1 5 A8.2i 5 A8.2i 5 A8.3i 5 A8.3i 5 A8.4i		Y	8/26/2016
5 A8.1 5 A8.2 5 A8.2 5 A8.3 5 A8.3 5 A8.4	, ,	Y	8/26/2016
5 A8.2i 5 A8.3i 5 A8.3i 5 A8.4i		Y	8/26/2016
5 A8.2l 5 A8.3i 5 A8.3l 5 A8.4i		Y	8/26/2016
5 A8.3i 5 A8.3i 5 A8.4i		Y	8/26/2016
5 A8.3l 5 A8.4a		Y	8/26/2016
5 A8.4a		Y	8/26/2016
		Y	8/26/2016
5 A8.4l		Y	8/26/2016
5 A8.4		Y	8/26/2016
5 A8.40		Y	8/26/2016
5 A8.40		Y	8/26/2016
5 A8.4		Y	8/26/2016
5 A8.5		Y	8/26/2016
5 A8.6		Y	8/26/2016
5 A8.7		Y	8/26/2016
5 A8.8	·	Y	8/26/2016
5 A9.1		Y	8/26/2016
		· ·	3,12,12310
5 S0.1	1 Holddowns added at Office/Staff Room area	Y	8/26/2016
5 S0.2	·	Y	8/26/2016
5 S1.1	·	Y	8/26/2016
	and Private Dining		-11
5 S1.2		Y	8/26/2016
5 S1.3	2 Foundation added for new low roof near wing ends, new detail callout 3/S2.2 added	Y	8/26/2016

5	S1.4	Beams and joists added at Marketing/Office area, framing updated at Elev. Equip Room 155, framing updated	Υ	8/26/2016
		at Office/Can Wash area		
5	S1.5	Framing information added for lower roofs at wing ends	Y	8/26/2016
5	S1.6	Framing information added for lower roof at wing end	Y	8/26/2016
5	S1.7	Non-typical window head heights called out on plan	Y	8/26/2016
5	S1.8	Chase key note relocated	Y	8/26/2016
5	S1.9	Chase key note relocated	Y	8/26/2016
5	S1.10	Chase key note relocated	Y	8/26/2016
5	S1.11	Chase key note relocated	Y	8/26/2016
5	S1.12	Chase key note relocated	Y	8/26/2016
5	S1.14	Chase key note relocated	Y	8/26/2016
5	S1.15	Chase key note relocated	Y	8/26/2016
5	S2.1	Date for soils report updated	Y	8/26/2016
5	S2.2	Detail 1 revised per soils report, detail 3 added to set, details 17 and 18 revised	Y	8/26/2016
5	S2.3	Detail 1 revised	Y	8/26/2016
5	S2.8	Details 6 and 11 revised	Y	8/26/2016
5	S3.5	Details 1, 2 and 9 revised. Details 10-13 added to sheet	Y	8/26/2016
5	M1.1	Rear foyer increased in size, plumbing revised at A8 unit 122	Y	8/26/2016
5	M1.5	Rear foyer increased in size, key note added for condensate drain to be provided for future PTAC's	Y	8/26/2016
5	M1.6	Key note added for condensate drain to be provided for future PTAC's	Y	8/26/2016
5	M1.7	Key note added for condensate drain to be provided for future PTAC's	Y	8/26/2016
5	M1.8	Key note added for condensate drain to be provided for future PTAC's, hose bib added at deck	Y	8/26/2016
5	M2.1	Detail 9 revised	Y	8/26/2016
5	M2.4	Gas fireplace has been removed from piping schematic	Y	8/26/2016
5	M2.6	Rear foyer increased in size. Can Wash/Office area updated	Y	8/26/2016
5	M3.1	Exhaust fan in Beauty room revised, transfer grille between Kitchen and Dining updated, layout of kitchen	Y	8/26/2016
		mechanical equipment at patio between Staff and Private dining updated		
5	M3.2	Gas fireplace in Reading room revised to be electric	Y	8/26/2016
5	M3.6	Dryer routing updated on all floors	Y	8/26/2016
5	M3.7	Dryer routing updated on all floors	Y	8/26/2016
5	M4.0	Detail 2 revised to show side wall dryer venting, detail 7 removed, detail 14 added	Y	8/26/2016
5	M4.1	Details 2 and 14 revised	Y	8/26/2016
5	M4.2	Unitstrut in detail 3 revised, note added	Y	8/26/2016
5	M5.3	Clarification on fire sprinklers	Y	8/26/2016
5	E1.0a	Rear foyer area revised	Y	8/26/2016
5	E1.0b	Rear foyer area revised	Y	8/26/2016
5	E1.0c	Rear foyer area revised	Y	8/26/2016
5	E1.1L	Rear foyer area revised	Y	8/26/2016
5	E1.1P	Rear foyer area revised	Y	8/26/2016
5	E1.5L	Laundry room updated	Y	8/26/2016
5	E1.5P	Laundry room updated	Y	8/26/2016
5	E1.6L	Laundry room updated	Y	8/26/2016
5	E1.6P	Laundry room updated	Y	8/26/2016
5	E1.7P	Electric panel relocated in attic catwalk	Y	8/26/2016

5	E2.2b	Detail 11 revised	Υ	8/26/2016
5	E3.1	Rear foyer area revised, Office/Marketing area modified with low voltage equipment	Υ	8/26/2016
5	E3.5	Laundry room updated	Υ	8/26/2016
5	E3.6	Laundry room updated	Υ	8/26/2016
5	E4.2	Detail 12 added to sheet	Υ	8/26/2016
5	E5.0	Office/Can Wash area updated. Kitchen equipment at patio between Staff and Private Dining updated	Υ	8/26/2016
5	E5.1	Low voltage information added to Office/Marketing detail. Switches moved out of pantry area in Manager	Υ	8/26/2016
		and Co-Manager units. HDMI connection called out in Media Room		
5	E5.5	Transfer fan in B2 unit relocated	Υ	8/26/2016
5	E5.9	Lights added at B28 unit, transfer fan in BD1 unit relocated	Υ	8/26/2016
5	SC1.1	Rear foyer increased in size	Υ	8/26/2016
5	SC2.1	Specifications for SEF-1 updated	Υ	8/26/2016