

3/27/02 Guardrail not 36", No Grasable HR,
Top Rise 1" more than preceding, measurement
Too Large at step + bottom of guardrail



Owner says a block pad will be placed
on grade to achieve Last step. JB

4/16/02 reinspected ok JB

#014531

424-A-14