

Pipeline Specialists



Everett J. Prescott, Inc.

Home Office
P.O. Box 600
32 Prescott Street
Gardiner, Maine 04345

Pipeline Specialists



Everett J. Prescott, Inc.

HYDRANT FLOW TEST REPORT

Contractor: Acorn Engineering

Date: 9/11/18

Job Site: 165 Presumpscot St.

Time: 12:15 PM

Portland, ME

Hydrant #1 Location: Behind Eldredge Lumber

Hydrant #2 Location: _____

Hydrant #3 Location: _____

Hydrant #4 Location: _____

RESULTS

Hydrant	#1	#2	#3	#4
Static Pressure	<u>102</u> PSI	____ PSI	____ PSI	____ PSI
Flow Rate	<u>1355</u> GPM	____ GPM	____ GPM	____ GPM
Shows Pressure	<u>24</u> PSI	____ PSI	____ PSI	____ PSI
Residual Pressure (when flowing Hydrant # __)	<u>40</u> PSI	____ PSI	____ PSI	____ PSI
Nozzle Size	<u>2.5</u>	____	____	____

Remarks: Only one hydrant

Test made by David S. Robinson

Witnessed by _____