



Second Floor New

Windows adjacent to stairway landings are all greater than 36" horizontally and 60" vertically off the landing and are not considered hazardous according to R308.4.7

PRODUCT CODE	SIZE	Header	REVERSED	COUNT
30X80 COLONIAL A 1	2'-6"	Double 2x8	NO	1
CW135 (S08)	3'4 13/16" x 2'4 3/8"	Double 2x8	NA	6
30X36 DOUBLE HUNG 1	2'-6" x 3'-0"	NA	NA	2

Smoke and carbon monoxide detectors will be installed in accordance with R314 and R315. Location and quantity to be determined by the electrician during construction.