

CODE CASE DETAILED REPORT RR1800059 FOR CITY OF PORTLAND

	NOV Required Di		Opened Date: Closed Date:	04/20/2018 NOT CLOSED
Inspection Number Code Case 001164-2018	Inspection Type Code Description FP Routine Fire Inspection	Inspection Date Code Comments 3/29/2018	Inspection Standard Deadline Date In Violation	
NFPA 101-4.5.3.2, 7.1.1	0.1 The means of egress shall remain from and unobstructed.	ee IMMEDIATELY remove all obstructions to the means of egress. All the floors in rear stairwell have storage obstructing the means of egress. 2nd and 3rd floor front stairwell have storage. Owner given 24 hours to have tenants remove items.	3/30/2018	
NFPA 101-31.2.2.1	1-hour fire rated doors and assembli required, including self-closing and self-latching mechanisms.	es All apartmenr entry doors; front and rear stairwells. The basement door will require one as well.	3/29/2019	
NFPA 101-Ch. 8	The fire barrier, including walls, ceilings, floors, etc. must be maintained with the minimum require fire rating.	Cockloft access panel at the top of the rear stairwell must be fire rated.	4/28/2018	
NFPA 101-9.1.2; NFPA 7	70 All electrical equipment must comply with the National Electric Code.	In the basement a set of Washers and dryers (W/D) are blocking the electrical panels and the Portland Water District shut off on the Alpha wall. Relocation of the W/D recommended.	4/29/2018	
NFPA 101-Ch. 8	The fire barrier, including walls, ceilings, floors, etc. must be maintained with the minimum require fire rating.	Repair the hole in the 3rd floor wall rear stairwell.	4/28/2018	